

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01 (Claims & Performance Management)
Singapore 068897

Our File No: CS/AIS23007153/KQP3M4**Date:** 31/07/2023**REFERENCE**

Insured/Claimant: LIM GUANG CHENG ROGER Policy No: SP2004601407-01
Date of Loss: 11/07/2023 Nature of Claim: OD Claim No: 202332010561

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLA6947G**
Make & Model: VOLVO S60, 2.0 T5 ABS D/AIRBAG 2WD (A) Engine No: B4204T111470192
Reg. Date: 11/03/2016 (Man. Year: 2015) Chassis No: YV1FS40LDG2406597
Colour: Metallic Grey Odometer: 118135 km
Engine Capacity: 1969 cc
Market Value/New Car Price: S\$53,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/45 ZR17 Rear Tyre Size: 235/45 ZR17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 7 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,298.90	5,774.90	2,524.00	30.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	500.00	500.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,298.90	6,274.90	3,024.00	32.52
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	8,698.90	5,674.90	3,024.00	34.76
+ GST 8.00/8.00% (\$\$)	695.91	453.99	241.92	34.76
Nett Amount (\$\$)	9,394.81	6,128.89	3,265.92	34.76

INSPECTION

Date of Assignment: 14/07/2023

Date Inspected: 17/07/2023 Inspected At:

Alan's United Auto Pte Ltd (HQ)
Blk 7 Sin Ming Industrial Estate, #01-76
Singapore 575642

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Jul 2023)
Parts:	143	VOLVO S60 2.0 T5 ABS D/AIRBAG 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA6947G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE ASSY (WCP)	Cracked	780.00 F	*780.00 F
2	1		*FRONT GRILLE AIR COWLING (WCP)	Serviceable	750.00 F	*- F
3	1		*FRONT BUMPER FASCIA (WCP)	Bent	1,900.00 F	*1,900.00 F
4	1		*FRONT BUMPER REINFORCEMENT (WCP)	Repair	1,300.00 F	*- F
5	1		*FRONT BUMPER SPONGE (WCP)	Cracked	500.00 F	*500.00 F
6	2		*FRONT BUMPER SIDE RETAINER (WCP)	Serviceable	240.00 F	*- F
7	7		*FRONT BUMPER TOP CLIP (WCP)	Necessary	49.00 F	*49.00 F
8	1		*N/S HEADLAMP ASSY (WCP)	Mtg Cracked	1,900.00 F	*1,900.00 F
9	1		*N/S AIR CON CONDENSER SIDE GUIDE (WCP)	Cracked	80.00 F	*80.00 F
10	1		*FRONT NO.PLATE WITH BOX	Dented	50.00 FS	*45.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	7,549.00	5,254.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	749.90	520.90
Total Parts (\$\$)	8,298.90	5,774.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY AND SPRAY REPLACED PARTS	New	500.00	250.00
2	TO REMOVE, CUT-OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ABOVE PARTS	New	500.00	250.00
Gross Labour Cost (S\$)			1,000.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >