



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBR 6863T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT FENDER	NOT NECESSARY	145.00	-
1	FRONT WHEEL AXLE	NOT NECESSARY	75.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	155.00	-
1	WINDSHIELD	NOT NECESSARY	115.00	-
1	HEADLAMP COWLING	BROKEN	450.00	450.00
1	HEADLAMP	NOT NECESSARY	515.00	-
1	FRONT SIGNAL LAMP SET OF 2	BROKEN	85.00	85.00
1	FRONT SIDE MIRROR SET OF 2	GRAZED	115.00	115.00
1	DIGITAL METER	NOT NECESSARY	650.00	-
1	HANDLE CLIP SET OF 2	BENT	220.00	220.00
1	HANDLE CLIP BALANCER SET OF 2	GRAZED	55.00	55.00
1	STEERING STEM BEARING	NOT NECESSARY	90.00	-
1	FRONT FORK STEERING FORK BRIDGE	NOT NECESSARY	380.00	-
2	FRONT FORK STEERING STEM	NOT NECESSARY	350.00	-
2	FRONT TOP COWLING INNER L/R	BROKEN	225.00	225.00
2	SIDE FAIRING INNER L/R	BROKEN	315.00	315.00
2	SIDE FAIRING OUTER L/R	BROKEN	420.00	420.00
1	SET DECAL	NECESSARY	200.00	120.00
1	BRAKE LEVER	GRAZED	58.00	58.00
1	CLUTCH LEVER	GRAZED	58.00	58.00
2	FRONT FOOTREST L/R	GRAZED	115.00	115.00
2	FRONT FOOTREST HOLDER L/R	NOT NECESSARY	155.00	-
1	BRAKE PEDAL	GRAZED	68.00	68.00
1	GEAR PEDAL	BENT	72.00	72.00
1	TANK COVER L/R	NOT NECESSARY	250.00	-
1	TANK COVER CENTRE	NOT NECESSARY	115.00	-
2	TAIL OUTER COVER L/R	NOT NECESSARY	225.00	-
1	REAR FOOTREST SET OF 2	NOT NECESSARY	115.00	-
2	REAR FOOTREST HOLDER L/R	NOT NECESSARY	185.00	-
1	EXHAUST PIPE	TO REPAIR SEE LABOUR	650.00	-

Report Ref No. CS3/ASM22003561/Dnp3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXHAUST PIPE COVER 1	GRAZED	65.00	65.00
1	EXHAUST PIPE COVER 2	GRAZED	75.00	75.00
1	EXHAUST PIPE COVER 3	BROKEN	60.00	60.00
1	REAR SWING ARM	GRAZED	520.00	520.00
1	REAR MUDGUARD	GRAZED	105.00	105.00
1	REAR BRAKE DISC	NOT NECESSARY	175.00	-
1	REAR WHEEL DISC	NOT NECESSARY	105.00	-
2	WHEEL RIM SET OF 2	NOT NECESSARY	450.00	-
2	WHEEL BEARING F/R	REAR NECESSARY	116.00	58.00
	LESS 10% DISCOUNT		-829.70	-325.90
			7,467.30	2,933.10
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BOX (SN)	GRAZED	350.00	220.00
1	REAR BOX BRACKET (SN)	NOT NECESSARY	125.00	-
1	FRONT NUMBER PLATE STICKER (SN)	NOT NECESSARY	15.00	-
1	FRONT P PLATE STICKER (SN)	NOT NECESSARY	15.00	-
			505.00	220.00
	<u>LABOUR</u>			
	TOWING CHARGES.	NOT NECESSARY	100.00	-
	REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS, CHECK WIRING AND LIGHTING SYSTEM. INCLUSIVE OF THE REPAIR OF EXHAUST PIPE.		700.00	300.00
	TO REPLACE AND BALANCE FRONT AND REAR WHEEL RIMS.		150.00	50.00
	TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING.		450.00	150.00
	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES.		150.00	50.00
	SPRAY PAINTING.		600.00	200.00
			2,150.00	750.00
	GRAND TOTAL		10,122.30	3,903.10



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,100.00
---	--	--	-----------------

Report Ref No. CS3/ASM22003561/Dnp3e2-1

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.