

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG123007201/UVY3Q2**Date:** 27/07/2023**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : SNC8920K **Insured Vehicle No :** SKH5599J
 Date of Loss: 14/07/2023 Nature of Claim: TP Claim No: CDMPG23001726

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNC8920K**
 Make & Model: ADIVA AD1 200, 190cc 3W Engine No: L15B6052300
 Reg. Date: 23/11/2021 (Man. Year: 2021) Chassis No: GK82201882
 Colour: Grey Odometer: 40078 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,520.80	6,586.32	10,934.48	62.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,300.00	2,510.00	1,790.00	41.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,820.80	9,096.32	12,724.48	58.31
Approved Total (Overridden) (S\$)		7,200.00		
Nett Amount (S\$)	21,820.80	7,200.00	14,620.80	67.00

INSPECTION

Date of Assignment: 14/07/2023
 Date Inspected: 18/07/2023 Inspected At: Huat Hock Motor Workshop (HQ)
 BLK 3012 BEDOK NORTH AVE 4, #01-2054
 BEDOK INDUSTRIAL PARK E
 Singapore 1648
 Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Jul 2023)	
Parts:	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNC8920K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP RH	Cracked	1,550.70 F	*1,550.70 FL
2	1		*FRONT BONNET	Not Necessary	981.90 F	*- FL
3	1		*FRONT BUMPER SIDE RETAINER RH	Bent	62.90 F	*35.00 FL
4	1		*FRONT FENDER RH	Badly Dented	817.80 F	*368.40 FL
5	1		*FRONT FENDER SPLASH GUARD	Twisted / Deformed	132.60 F	*132.60 FL
6	1		*FRONT DOOR RH	Badly Dented	948.70 F	*948.70 FL
7	1		*FRONT DOOR SIDE MIRROR ASSEMBLY RH	Cut / Damaged	310.70 F	*310.70 FL
8	1		*FRONT DOOR SIDE MIRROR COVER RH	Not Necessary	112.80 F	*- FL
9	1		*FRONT DOOR RH TRIM BOARD	Not Necessary	318.10 F	*- FL
10	1		*FRONT DOOR RH WEATHERSTRIP	Not Necessary	190.20 F	*- FL
11	1		*FRONT DOOR RH LOCK ASSEMBLY	Not Necessary	233.60 F	*- FL
12	1		*FRONT DOOR RH DOOR HANDLE (OUTER)	Not Necessary	89.10 F	*- FL
13	1		*FRONT DOOR HINGE RH (UPPER)	Bent	68.20 F	*68.20 FL
14	1		*FRONT DOOR HINGE RH (LOWER)	Bent	68.20 F	*68.20 FL
15	1		*FRONT DOOR CHECK RH	Not Necessary	62.10 F	*- FL
16	1		*FRONT DOOR RH WINDOW GLASS REGULATOR	Bent	301.70 F	*282.00 FL
17	1		*FRONT LOWER ARM RH	Not Necessary	216.90 F	*- FL
18	1		*FRONT WHEEL BEARING RH	Bent	201.90 F	*201.90 FL
19	1		*FRONT KNUCKLE ASSEMBLY RH	Bent	329.10 F	*329.10 FL
20	1		*FRONT WHEEL HUB RH	Bent	310.90 F	*310.90 FL
21	1		*RH CENTER DOOR PILLAR	Repair	662.90 F	*- FL
22	1		*REAR DOOR RH	Dented / Bent	955.70 F	*955.70 FL
23	1		*REAR DOOR RH TRIM BOARD	Not Necessary	320.90 F	*- FL
24	1		*REAR DOOR RH WEATHERSTRIP	Not Necessary	192.10 F	*- FL
25	1		*REAR DOOR RH LOCK ASSEMBLY	Not Necessary	240.90 F	*- FL
26	1		*REAR DOOR RH WINDOW GLASS REGULATOR	Bent	300.80 F	*280.00 FL
27	1		*REAR DOOR RH HANDLE (OUTER)	Not Necessary	89.10 F	*- FL
28	1		*REAR RH FENDER	Repair	838.10 F	*- FL
29	1		*REAR RH FENDER SPLASH GUARD	Not Necessary	133.60 F	*- FL
30	1		*REAR BUMPER	Repair	1,250.10 F	*- FL
31	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	63.10 F	*- FL
32	1		*RH SIDE SKIRTING	Deformed / Torn	428.10 F	*428.10 FL
33	1		*REAR TAILLAMP RH	Not Necessary	529.10 F	*- FL
34	1		*FRONT BUMPER	Cut	1,128.20 F	*862.70 FL
35	1		*SET REAR DOOR TRIM BOARD CLIPS	Not Necessary	40.00 FS	*- FS
36	1		*SET REAR FENDER SPLASH GUARD CLIPS	Not Necessary	40.00 FS	*- FS
37	1		*SET FRONT FENDER SPLASH GUARD CLIPS	Necessary	40.00 FS	*40.00 FS
38	1		*SET FRONT DOOR TRIM BOARD CLIPS	Not Necessary	40.00 FS	*- FS
39	1		*SET REAR BUMPER CLIPS	Not Necessary	40.00 FS	*- FS
40	1		*SET FRONT BUMPER CLIPS	Necessary	40.00 FS	*40.00 FS
41	1		*FENDER PANEL SEALANT	Not Necessary	100.00 FS	*- FS
42	1		*REAR TYRE RH	Not Necessary	380.00 FS	*- FS
43	1		*REAR TYRE RIM RH	Cut	980.00 FS	*400.00 FS
44	1		*FRONT TYRE RH	Cut	400.00 FS	*400.00 FS
45	1		*FRONT TYRE RIM RH	Serviceable	980.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CARRY OUT ANTI-RUST TREATMENT	New	120.00	90.00
2	REWIRING TO FACILITATE WORKS	New	120.00	20.00
3	TRANSFER OF FRONT AND REAR DOOR MECHANISM	New	280.00	120.00
4	REMOVE AND REFIT ALL TRIMS ,UPHOLSTERY GARNISH AND ALL NECESSARY TO FACILITATE REPAIR WORKS	New	320.00	80.00
5	TO CONDUCT 4 WHEEL ALIGNMENT	New	180.00	80.00
6	LABOUR TO REMOVE AND REPLACE DAMAGED PARTS (INCLUDING REFITTING AND REPOSITIONING OF REPLACED PARTS)	New	1,300.00	800.00
7	SPRAY PAINTING MATERIALS AND RESPRAY OF ALL AFFECTED AND REPLACED PARTS NECESSARY FOR PAINTWORK	New	1,500.00	1,200.00
8	TO REMOVE UNDER CARRIAGE & INSTALL NEW PARTS (INCLUDING SHOCK ABSORBER LOWER ARM, KNUCKLE ,BEARING ETC)	New	480.00	120.00
Gross Labour Cost (S\$)			4,300.00	2,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >