

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/III23007210/UNY3E2**Date:** 25/07/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : GBH5892T**Insured Vehicle No :** SHD2527T

Date of Loss: 29/03/2023

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBH5892T**

Make & Model: TOYOTA DYNA 1.5T, 3.0 (A)

Engine No: 1KD2805175

Reg. Date: 20/07/2018 (Man. Year: 2018)

Chassis No: JTFAT35Y20K210770

Colour: White

Odometer: 108601 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/75 R16

Rear Tyre Size: 155 R12 (D)

Front Left Side: Bridgestone 7 mm

Rear Left Side: GREEN-MAX 7/7 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side: GREEN-MAX 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,689.27	653.74	2,035.53	75.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	980.00	620.00	38.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,289.27	1,633.74	2,655.53	61.91
Approved Total (Overridden) (S\$)		1,300.00		
Nett Amount (S\$)	4,289.27	1,300.00	2,989.27	69.69

INSPECTION

Date of Assignment: 17/07/2023

Date Inspected: 17/07/2023

Inspected At: Autocity Pte Ltd (HQ)
32 Kaki Bukit Crescent
Singapore 416262

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Jul 2023)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH5892T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WHEEL GUARD ASSY - RH	Distorted	871.65 FL	*871.65 FL
2	1		*REAR WHEEL HUB SHAFT - RH	Not Necessary	861.95 FL	*- FL
3	1		*REAR WHEEL BEARING	Not Necessary	180.90 FL	*- FL
4	1		*REAR WHEEL HUB SHAFT OIL SEAL	Not Necessary	151.20 FL	*- FL
5	1		*REAR WHEEL RIM - RH	Repair	180.00 FS	*- FS
6	1		*REAR TYRE	Not Necessary	160.00 FS	*- FS
7	1		*REAR SIDE PANEL LOWER MENBER - RH	Repair	800.00 FS	*- FS
					Sub Total (\$\$)	3,205.70
					- List Item Discount on L Items 25.00/25.00% (\$\$)	516.43
					Total Parts (\$\$)	2,689.27
						653.74

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REFIX FRONT UNDERCARRIAGE	New	200.00	0.00
2	TO RESPRAY PAINTING AND ETC	New	600.00	500.00
3	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS	New	800.00	480.00
Gross Labour Cost (\$)			1,600.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >