

(08/11/13) wsf

ASS. REC. BY: *JKM*

REF:

*CS/LIP 23007222/Rqy3*

*430N*

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *GBJ 2464E*

at Workshop m/s *E-CULTURE*

of *1, DEFU LANE 6*

Insured: *LIP*

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *66K*

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: *4* days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: *GBJ 2464E* Yr Regn: *2019 / FEB*

Type: M.Car / M.Cycle / Bus / ~~Van~~ / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *TOYOTA HIACE* JAR MT c.c *2982*

Colour: *WHITE* A/C: Insured / Std / NI / NA

Sp. Reading: *149496* T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: *JTFH T02 P600 247485*

Gen. Cond: Good / ~~Fair~~ / Poor / Burnt

Steering: ~~In order~~ / Jammed / Leaked / Burnt or

Brake: ~~In order~~ / Jammed / Leaked / Burnt or

Modi: Nil / ~~S/Rim~~ / STD A/Rim or

Tyre Size: F: *195 R15LT*

R: *^ ^*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *GREENLANDER*

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. *6* mm R/Bal. *6* mm

L/Bal. \_\_\_\_\_ mm L/Bal. \_\_\_\_\_ mm

D.O.A. *13/07/23* D.O.I. *17/07/23*

Survey held at *1, DEFU LANE 6*

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*REPAIR LIMIT - 52K*

*Repair finalised LS @ 1350, 4 days (Red @ 6527-71, 83%)*

Date/Time, File Pass to?  Prel. Report

*1) 04/8/2013*  Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: *4*

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:	
Transportation:	
_____ S + RS _____ SI	
Photos	
Others	
TOTAL	

Add Fee:  Site Insp (\$ )

Interview (\$ )

Tech. Invs (\$ )

Weekend (\$ )

Report Format : *TP*

Lump Sum / I.B. (\$) *1350* )



# E-CULTURE AUTOMOTIVE PTE LTD

*One Stop Automotive Solution*

Blk 166A Teck Whye Cres #19-345 Singapore 681166

UEN: 202225515N | E-mail: info.ecauto@gmail.com

Contact No : 8757 9296 / 9816 8803

## ESTIMATE

**Liberty Insurance Pte Ltd**  
51 Club Street, #03-00 Liberty House  
Singapore 069428  
Tel: 6221 8611 Fax: 6226 3360

Attn : Motor Claim Department

VEHICLE NO : GBJ2464E

MAKE / MODEL : TOYOTA HIACE VAN TURBO 5DR MT

CHASSIS NO : JTFHT02P600247485

OWN INSURANCE : Allianz Insurance Singapore Pte. Ltd.

3RD PARTY VEHICLE NO : SJR4783J

D.O.A ; 13.07.2023

### CLAIM DETAIL : LIST PRICE (\$\$)

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE X nn	1	\$ 1,969.90	\$ 1,969.90 X
2	TAILGATE EMBLEM 'LOGO' X nn	1	\$ 86.50	\$ 86.50 X
3	TAILGATE WINDSCREEN MOULDING X nn	1	\$ 126.70	\$ 126.70 X
4	TAILGATE WEATHERSTRIP X nn	1	\$ 474.70	\$ 474.70 X
5	TAILLAMP RH h n /	1	\$ 300.90	\$ 300.90
6	REAR BUMPER UPPER COVER RH g n /	1	\$ 69.84	\$ 69.84
7	REAR BUMPER UPPER COVER RETAINER RH ? X nn	1	\$ 298.00	\$ 298.00 X
8	REAR BUMPER g n /	1	\$ 475.80	\$ 475.80
9	REAR BUMPER SIDE RETAINER LH/RH RH-B / LH-X nn	1 /	\$ 50.70	\$ 101.40 X
10	REAR END PANEL EXTENSION RH X nn	1	\$ 311.63	\$ 311.63 X
11	REAR QUARTER PANEL RH requir	1	\$ 1,921.89	\$ 1,921.89 X
12	REAR QUARTER AIR VENT RH ? X nn	1	\$ 112.35	\$ 112.35 X

897.24  
897.24  
20%  
672.93

TOTAL PRICE : \$ 6,249.61  
LIST LESS 25% : \$ 1,562.40  
**SUB TOTAL PRICE : \$ 4,687.21**

### CLAIM DETAIL : PARTS S/NETT(\$\$)

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL S/N PRICE
1	TAILGATE WINDSCREEN SEALANT X nn	1	\$ 60.00	\$ 60.00
2	TAILGATE WINDSCREEN INNER SEAL X nn	1	\$ 60.00	\$ 60.00
3	TAILGATE 70KM/H STICKER X nn	1	\$ 20.00	\$ 20.00
4	TAILGATE COMPANY AD STICKER X nn	1	\$ 220.00	\$ 220.00
5	REAR QUARTER PANEL COMPANY AD STICKER h n /	1	\$ 400.00	\$ <del>400.00</del> 230
6	REAR BUMPER CLIP SET h n /	1	\$ 50.00	\$ <del>50.00</del> 30
7	REVERSE SENSOR X nn	1	\$ 280.00	\$ 280.00

**S/NETT TOTAL PRICE \$ 1,090.00**

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	DESCRIPTION	PRICE
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS; REPLACE THE DAMAGED PARTS AND COMPONENTS.	\$ <del>400</del> 800.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED AND REPAIRED AREAS	\$ <del>300</del> 800.00
3	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	\$ <del>Xm</del> 80.00
4	LABOUR CHARGE TO CHECK ELECTRICAL WIRING AND TEST REAR LIGHT FUNCTIONALITY	\$ <del>30</del> 80.00
5	LABOUR CHARGE TO TRANSFER TAILGATE MECHANISM	\$ <del>Xm</del> 120.00
6	REMOVE-REFIX TAILGATE WINDSCREEN GLASS	\$ <del>Xm</del> 120.00
7	TO DISMANTLE & REPLACE REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ <del>60</del> 100.00

790

LABOUR TOTAL PRICE: \$ 2,100.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Same  
Hj 9040068  
4 days  
H/S  
17/07/23 =  
Resy after repair

672.93  
230.00  
790.00  

---

1692.93  
202  
1394

4/5 - \$1,350 / 4 days