



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 3314P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FOG LAMP - RH	NOT NECESSARY	293.25	-
1	FRONT CORNER PANEL - RH	TO REPAIR SEE LABOUR	468.21	-
1	FRONT DOOR ASSY - RH	TO REPAIR SEE LABOUR	5,542.30	-
1	FRONT DOOR LAMP - RH	NOT NECESSARY	195.03	-
1	SIDE MIRROR STAY - RH	BENT	612.86	612.86
1	SIDE MIRROR (BIG) - RH	BENT	177.68	177.68
1	SIDE MIRROR STAY BRACKET UPPER - RH	BENT	124.66	124.66
1	SIDE MIRROR STAY BRACKET LOWER - RH	BENT	124.66	124.66
1	SIDE MIRROR STAY BRACKET LOWER COVER - RH	MISSING	135.47	135.47
	LESS 25% DISCOUNT		-1,918.53	-293.83
			5,755.59	881.50
	<u>LABOUR</u>			
	LABOUR TO RENEW ALL ABOVE PARTS & KNOCK & WELD. INCLUSIVE OF THE REPAIR OF FRONT CORNER PANEL - RH AND FRONT DOOR ASSY - RH.		1,000.00	500.00
	TO RUST PROOFING ON AFFECTED AREA.	NOT NECESSARY	850.00	-
	TO SPRAY & PAINTING AT ACCIDENT AFFECTED AREA.		1,000.00	300.00
			2,850.00	800.00
GRAND TOTAL			8,605.59	1,681.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,300.00

Report Ref No. CS/LPC23007225/Uny3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.