



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC23007225/Uny3e2 Date: 25/07/2023 Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	XD 9143G	Veh. Inspected	XE 3314P	
Policy No.		Coverage (\$)	0.00	
Claim No.	23/23/23/VC05/027683	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	17/07/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MITSUBISHI FUSO FV51 (M)	c.c	11967	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	FV51SJA20258	Colour	WHITE	
Odometer	548691 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	FRONWAY	6 mm	
L/H Front Tyre	295/80 R22.5	FRONWAY	6 mm	
R/H Rear Tyre	295/80 R22.5 (D/D)	KPATOS	6/6/6/6 mm	
L/H Rear Tyre	295/80 R22.5 (D/D)	KPATOS	6/6/6/6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	10/07/2023	Inspection Date	20/07/2023	
Survey held at	MAH LIAN MOTOR VEHICLE REPAIRER 38 DEFU LANE 9 SINGAPORE 539278			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	