



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)			Ref:	CS/SPF23007242/Kvy3e2
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1			Date:	28/07/2023
HEMMANT ROAD SINGAPORE 438675				
ATTN: LAI PENG CHONG			Code:	SPF
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	QX 693Y	Veh. Inspected	SMR 3550K	
Policy No.		Coverage (\$)	0.00	
Claim No.	ACS/105/009/2023/049 (LK)	Excess (\$)	0.00	
Assign From	LAI PENG CHONG	Assign Date	17/07/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA SHUTTLE (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	GP72001023	Colour	METALLIC BLACK	
Odometer	264082 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	KAPSEN	8 mm	
L/H Front Tyre	185/60 R15	KAPSEN	8 mm	
R/H Rear Tyre	185/60 R15	COMFORT MAX	9 mm	
L/H Rear Tyre	185/60 R15	COMFORT MAX	9 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	15/07/2023	Inspection Date	18/07/2023	
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	