

ASS. REC. BY:

REF:

SPF/ 23007242/KV

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD/TP/WS/TP RES/ QD RES/ EVA/ INV/ MV

To Inspect Vehicle No: _____

at Workshop m/s Thiam 1414

of _____

Insured: QX 693Y

Policy No. _____


Claims No. ACS/105/009/2023/049 (LK)

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 888k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMR 3550K Yr Regn: 12, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or WagonMake: Honda Shuttle C.C. 1496Colour: M. Black A/C: Insured / Std / NI / NASp. Reading: 264082 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GP7 2001023Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim orTyre Size: F: KapenR: Camfort max 185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 9 mmL/Bal. 8 mm L/Bal. 9 mmD.O.A. 15/7/23 D.O.I. 18/7/2023

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

Rn d/s

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

2017 21/8/23 @ 3200d Colours (red 4589.34, 58%)

Repair range \$3200-\$3500

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 27/7/23-typist

Report Format: TP

Lump Sum / H.B. (\$ 3200)

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Thiam Heng Huat Pte Ltd

176 SIN MING DRIVE #05-14 SIN MING AUTOCARE SINGAPORE 575721 Steven : HP-82636295

Vehicle No : SMR 3550 K
Make/Model : Honda Shuttle 1.5 Hybrid A
Chassis No : GP72001023
Year : 2019
D.O.A : 15.07.2023

NOT Authorized
11 Sep @ 3200h
Resurvey After Paint
4 days

Item	Description Parts	Qty	Price
1	Front bumper	1	\$ 767.80 ✓
2	Front bumper reinforcement 398	1	\$ 639.30 ✓
3	Front bumper side retainer L/R @ \$40.70	2	\$ 81.40 ✓
4	Front bumper bracket RH	1	\$ 59.40 X
5	Front bumper lower grille	1	\$ 368.80 X
6	Front bumper grille side cover RH	1	\$ 157.40 ✓
7	Front bumper side cover RH	1	\$ 95.00 ✓
8	Front bumper under cover	1	\$ 214.00 X
9	Front headlamp assy RH	1	\$ 1,128.30 ✓
10	Front radiator grille base	1	\$ 316.00 X
11	Front radiator grille chrome	1	\$ 338.40 X
12	Front fender RH 545.20	1	\$ 598.70 ✓
13	Front fender brace bracket RH	1	\$ 510.20 X
14	Front fender inner shield RH	1	\$ 197.40 ✓
15	Front fender enclosure RH	1	\$ 135.20 X
			\$ 5,607.30
		Less 20%	\$ 1,121.46
			\$ 4,485.84

S/NETT ITEM

16	Front bumper clips	1 set	\$ 38.00 ✓
17	Front radiator grille chrome emblem	1	\$ 115.00 X
18	Front wiper tank → 206 186.20	1	\$ 225.40 ✓
19	Front wiper tank neck hose	1	\$ 38.90 X
20	Front wiper tank cap	1	\$ 8.40 X
21	Front wiper tank motor	1	\$ 97.80 X
22	Front fender inner shield clips RH	1	\$ 30.00 ✓

Parts Total : \$ 5,039.34

LABOUR CHARGES & MISC

23	Check wiring, lighting, & centre locking system	\$ 50.00 20d
24	Lobour charges.	\$ 1,200.00 500d
25	Spray painting	\$ 1,000.00 600d
26	To cavity preservation on all affected areas.	\$ 100.00 30d
27	To conduct front wheel alignment.	\$ 120.00 X
28	To carry out diagnostic checks & & reset.	\$ 280.00 X

Labour Total : \$ 2,750.00

Sub Total : \$ 7,789.34

LKK Auto Consultants henceforth

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: