

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 4584A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEEP CUT/TORN	762.20	762.20
1	FRONT BUMPER SIDE RETAINER N/S	CRACKED	35.80	35.80
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT BUMPER FOG LAMP COVER N/S	DAMAGED	121.20	121.20
1	FRONT BUMPER LOWER LIP	GRAZED	385.20	385.20
1	HEADLAMP HID N/S	HOLDER CRACKED	1,759.20	1,759.20
1	HEADLAMP LOWER BRACKET N/S	CRACKED	86.50	86.50
1	FRONT FENDER N/S	BENT/BUCKLED	451.20	451.20
1	FRONT FENDER INNER SHIELD N/S	NOT NECESSARY	166.80	-
1	SET FRONT FENDER INNER SHIELD CLIPS N/S	NECESSARY	50.00	50.00
1	FRONT FENDER OUTER PROTECTOR N/S	GRAZED	280.20	280.20
1	FRONT SHOCK ABSORBER N/S	NOT NECESSARY	399.60	-
1	FRONT KNUCKLE ARM N/S	NOT NECESSARY	365.20	-
1	FRONT KNUCKLE ARM BEARING N/S	NOT NECESSARY	180.50	-
1	FRONT SPORT RIM N/S	DEEP CUT	850.00	850.00
	LESS 20% DISCOUNT		-1,188.72	-966.30
			4,754.88	3,865.20
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO CONDUCT WHEEL ALIGNMENT.		120.00	80.00
	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE.	NOT NECESSARY	150.00	-
	TO RESET & REPROGRAMME SYSTEM.		100.00	80.00
	TO SPRAY RUST PROOFING.		50.00	30.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.		680.00	580.00
	TO PUTTY & SPRAY PAINTING.		880.00	600.00
			2,030.00	1,390.00
	GRAND TOTAL		6,784.88	5,255.20



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	4,200.00
(TO ITS PRE-ACCIDENT CONDITION)	·

Report Ref No. CS/TP23007249/Uvy3m4

CHUA KANG SENG

Licensed Appraiser