



Your Ref : S3M04NZ5

Date: 25th July 2023

Our Ref : CS/HSB23007263/Tvp3m4

M/s HSBC Life (Singapore) Pte Ltd

10 Marina Boulevard

#48-01 Marina Bay Financial Centre Tower 2

Singapore 018983

(The Motor Claims Department)

Attn: Garnet Low

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SHA 1849L
ACCIDENT ON 08/07/2023**

Instruction was received to inspect the vehicle Reg. No. SHA 1849L. The inspection was conducted on 18/07/2023 at the premises of M/s Comfortdelgro Engineering Pte Ltd, 59 Loyang Drive, Singapore 508969.

The following vehicle information was recorded:

Registration Number	: SHA 1849L
Make/Model	: Hyundai I40 1.7 Crdi F/L At Abs Airbag 4dr
Year of Registration	: 2016
Body Colour	: Blue
Chassis Number	: KMHLB41UMHU096550
Engine Capacity	: 1685 cc

The vehicle caught fire. The cause of fire probably due to engine compartment short circuit. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Book Value	S\$	25,651.16 (est)
Less: LTA Reimbursement Value (RV)	(S\$	19,612.00)
Nett Liability	S\$	6,039.16
	=====	

Vehicle Inspected By:



MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.