From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd. 8 Temasek Boulevard

#04-01 Suntec Tower Three

Singapore 038988 Singapore 408933

Attn: 20 Jul 2023 Melody Teoh Date:

Preliminary Advice

Vehicle No : SNJ6076Z Accident Date : 13/07/2023 Policy No. : DMPG23000041 Make : HONDA VEZEL

Assignment Date : 18/07/2023 Excess : S\$0.00 Date of Inspection : 19/07/2023 Est. Duration of Repair : 10

Inspection At : SV AUTOWORKS PTE LTD (HQ)

8 KAKI BUKIT AVENUE 4, #02-24 PREMIER @ KAKI BUKIT

SINGAPORE 415875

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 45,594.48 |
|-----------------------------|------|-----------|
| Revised Amount | :S\$ | 24,405.40 |
| Check Items (Estimated) | :S\$ | 15,942.64 |
| Total | :S\$ | 40,348.04 |
| Luman Coma Banasia | .ОФ | 00 000 00 |
| Lump Sum Repair | :S\$ | 22.000.00 |

Total Loss Consideration

| New for Old Value | :S\$ | |
|--------------------|------|-----------|
| Pre-Accident Value | :S\$ | 42,000.00 |
| COE / PARF Rebate | :S\$ | 18,582.00 |
| Salvage Value | :S\$ | |
| Margin for Donair | .00 | 22 440 00 |

Margin for Repair 23,418.00 :S\$

Remarks

| (X) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kil | ndly |
|-------|--|------|
| | let us have your authorisation. | |

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: REPAIRER ABLE TO REPAIR THE VEHICLE AT LUMP SUM \$22,000.00. (X) Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.