

Wah Hong Motors & Credit Pte Ltd (Co.Reg.No:199806235M)

38 Toh Guan Road East, #01-57, Enterprise Hub

Singapore 608581

Tel: +65 6773 7377 Email: motor@wahhong.sg

INSURER: HL Assurance Pte Ltd (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	WH2106
Policy No:	MP321337	Date of Loss:	16/07/2023
Vehicle Reg. No.:	SMU4011C	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LEE WEE MING	Contact No:	+6583229384
Make/Model:	BMW 320I, 2.0 AT D/AB 4DR ABS HID NAV (A)	Vehicle Reg. Date:	24/12/2013
Vehicle Colour:	WHITE		
Engine No:	B5690511N20B20B	Chassis No:	WBA3B16030NP58502
Odometer:	110743 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		

Present Location: WAH HONG MOTORS & CREDIT PTE LTD (HQ)**COST OF CLAIMS**

	Amount
Parts	13,510.35
Miscellaneous Items	340.00
Labour	2,960.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	16,810.35
+ GST 8.00% (S\$)	1,344.83
Nett Amount (S\$)	18,155.18

This claim is handled by: TAN TING YI

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Jul 2023)

Parts: 143 BMW 320I 2.0 AT D/AB 4DR ABS HID NAV (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Wah Hong Motors & Credit Pte Ltd/SMU4011C/18/07/2023 17:02

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bonnet <i>bf</i>	0.00	0.00	*1,020.00 F
2	1		*Bonnet hinge RH/LH@2*\$125 <i>? Xnn</i>	0.00	0.00	*250.00 F
3	1		*Bonnet insulator <i>? Xnn</i>	0.00	0.00	*230.00 F
4	1		*Bonnet lock <i>? Xnn</i>	0.00	0.00	*85.00 F
5	1		*Bonnet lock cable <i>? Xnn</i>	0.00	0.00	*50.00 F
6	1		*Front fender RH/LH@2*\$830 <i>RH-X / LH-bf</i>	0.00	0.00	*1,660.00 F
7	1		*Front fender emblem Luxury@2*\$100 <i>m / LH (1pc)</i>	0.00	0.00	*200.00 F
8	1		*Front fender front shield RH/LH@2*\$150 <i>LH-? / RH-X nn</i>	0.00	0.00	*300.00 F
9	1		*Front fender rear shield RH/LH@2*\$150 <i>Xnn</i>	0.00	0.00	*300.00 F
10	1		*Headlamp RH/LH@2*\$1300 <i>LH-cm / RH-? Xnn</i>	0.00	0.00	*2,600.00 F
11	1		*Headlamp bracket RH/LH@2*\$215 <i>? Xnn</i>	0.00	0.00	*430.00 F
12	1		*Front bumper <i>de</i>	0.00	0.00	*1,280.00 F
13	1		*Front bumper side retainer RH/LH@2*\$29 <i>LH-nm / RH-Xnn</i>	0.00	0.00	*58.00 F
14	1		*Front bumper logo badge <i>m</i>	0.00	0.00	*85.00 F
15	1		*Center grille RH/LH@2*\$110 <i>cm</i>	0.00	0.00	*220.00 F
16	1		*Front bumper towing cover <i>Xnn</i>	0.00	0.00	*68.00 F
17	1		*Front bumper lower grille <i>Xnn</i>	0.00	0.00	*169.00 F
18	1		*Front bumper lower side grille RH/LH@2*\$85 <i>Xnn</i>	0.00	0.00	*170.00 F
19	1		*Front bumper lower side grille top chrome RH/LH@2*\$105 <i>Xnn</i>	0.00	0.00	*210.00 F
20	1		*Front bumper lower chrome <i>Xnn</i>	0.00	0.00	*38.00 F
21	1		*Front bumper lower cover <i>Xnn</i>	0.00	0.00	*169.00 F
22	1		*Brace panel <i>? Xnn</i>	0.00	0.00	*105.00 F
23	1		*Front bumper sponge <i>? Xnn</i>	0.00	0.00	*100.00 F
24	1		*Front bumper reinforcement <i>? Xnn</i>	0.00	0.00	*350.00 F
25	1		*Support panel <i>? Xnn</i>	0.00	0.00	*170.00 F
26	1		*Turbo intercooler <i>? Xnn</i>	0.00	0.00	*600.00 F
27	1		*Condenser <i>bf</i>	0.00	0.00	*1,150.00 F
28	1		*Radiator <i>? Xnn</i>	0.00	0.00	*800.00 F
29	1		*A pillar RH/LH (repair refer to labour)	0.00	0.00	*- F

F=Franchise part.

Sub Total (S\$)	12,867.00
+ Margin on L,N Items 5.00% (S\$)	643.35
Total Parts (S\$)	13,510.35

Wah Hong Motors & Credit Pte Ltd/SMU4011C/18/07/2023 17:02. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	Bonnet insulator clip <i>m</i> ✓	30	35.00
2	1	Center grille clip <i>m</i> ✓	30	35.00
3	1	Coolant ? <i>Xnn</i>	40	60.00
4	1	Front bumper clip <i>m</i> ✓	30	35.00
5	1	Front carplate with hoder <i>Xnn</i>	<i>11X</i>	35.00
6	1	Front fender front shield clip LH <i>m</i> ✓	30	35.00
7	1	Front fender front shield clip RH <i>Xnn</i>	<i>11X</i>	35.00
8	1	Front fender rear shield clip LH <i>m</i> ✓	30	35.00
9	1	Front fender rear shield clip RH <i>Xnn</i>	<i>11X</i>	35.00
Sub Total (S\$)				340.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	New	600	1,400.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	New	600	1,400.00
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	New	30	60.00
4	Remove and refit aircon condenser, radiator, related pipes and hoses, vacuum and refill aircon gas	New		100.00
Gross Labour Cost (S\$)				2,960.00

Wah Hong Motors & Credit Pte Ltd/SMU4011C/18/07/2023 17:02. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Paul
Hp 90010068
7 days
4/5
19/07/23
EXCESS: 775
REPAIR
Resy after repair