



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 9003C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER WITH BRACKET (N)	TO REPAIR SEE LABOUR	2,625.00	-
1	REAR BUMPER DOME O/S (N)	CRACKED	3,800.00	3,100.00
1	SET REAR BUMPER REVERSE SENSOR (N)	NOT NECESSARY	250.00	-
1	REAR EXHAUST (N)	BENT / TWISTED	1,815.00	1,620.00
1	REAR EXHAUST BRACKET (N)	SERVICEABLE	180.00	-
	LESS 10% DISCOUNT		-867.00	-472.00
			7,803.00	4,248.00
	<u>LABOUR</u>			
	TO CHECK WIRING.	NOT NECESSARY	80.00	-
	TO DISMANTLE & REFIX REAR REVERSE SENSOR.		80.00	40.00
	TO DISMANTLE & REPLACED REAR EXHAUST.		200.00	80.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER WITH BRACKET.		1,200.00	600.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	680.00
			3,060.00	1,400.00
GRAND TOTAL			10,863.00	5,648.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				4,500.00

Report Ref No. CS/INC23007310/Uny3e2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.