

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS23007318/KVY3Q2**Date:** 31/07/2023**REFERENCE**

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SLX3419M	Insured Vehicle No :	SLT9994A
Date of Loss:	17/07/2023	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX3419M	Engine No:	G3LCJU950394
Make & Model:	HONDA CIVIC, 1.6 (A)	Chassis No:	KMHK3811LJU094207
Reg. Date:	24/03/2018 (Man. Year: 2018)	Odometer:	66499 km
Colour:	Metallic Orange		
Engine Capacity:	998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,397.12	4,489.96	6,907.16	60.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,060.00	1,640.00	2,420.00	59.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	15,457.12	6,129.96	9,327.16	60.34

INSPECTION

Date of Assignment:	19/07/2023	
Date Inspected:	20/07/2023	Inspected At: Guan Motor Works (HQ) 176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721
Estimated Period of Repair:	10.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$6,136.16 NETT)

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Jul 2023)
Parts: 143	HONDA CIVIC 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLX3419M)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER TOP	Bent	516.90 FL	*516.90 FL
2	1		*REAR BUMPER BOTTOM	Cracked	185.00 FL	*185.00 FL
3	2		*REAR BUMPER REVERSE SENSOR	Shorted	390.00 FL	*390.00 FL
4	2		*REAR BUMPER SIDE LAMP	*Check	283.60 FL	*- FL
5	2		*REAR BUMPER SIDE RETAINER	Distorted	36.00 FL	*36.00 FL
6	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
7	1		*REAR BUMPER INNER REINFORCEMENT	Cracked	370.80 FL	*370.80 FL
8	1		*REAR TAILGATE	Bent	1,628.60 FL	*1,628.60 FL
9	1		*REAR TAILGATE CENTRE H LOGO	Necessary	30.70 FL	*30.70 FL
10	1		*REAR TAILGATE SIDE LAMP	O/S Cut	886.00 FL	*443.00 FL
11	1		*REAR TAILGATE OUTER HANDLE /GARNISH	Dented	226.00 FL	*226.00 FL
12	2		*REAR TAILGATE NUMBER PLATE LAMP	Serviceable	60.60 FL	*- FL
13	1		*REAR TAILGATE REVERSE CAMERA	*Check	573.90 FL	*- FL
14	1		*REAR WIPER MOTOR	*Check	263.90 FL	*- FL
15	1		*REAR TAILGATE INNER TRIM BOARD	*Check	253.00 FL	*- FL
16	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	*Check	60.00 FL	*- FL
17	2		*REAR TAILGATE DAMPER	Serviceable	364.00 FL	*- FL
18	1		*REAR TAILGATE TOP LOCK	Dented	208.00 FL	*208.00 FL
19	1		*REAR TAILGATE LOWER LOCK CATCH	Repair	28.80 FL	*- FL
20	1		*REAR TAILGATE WEATHERSTRIP	Distorted	112.20 FL	*112.20 FL
21	1		*REAR END PANEL	Bent	739.10 FL	*739.10 FL
22	1		*REAR END PANEL TOP GARNISH	Mtg Distorted	157.50 FL	*157.50 FL
23	1		*REAR SPARE TYRE PANEL	*Check	695.00 FL	*- FL
24	1		*REAR SPARE TYRE TOP BOARD	*Check	495.00 FL	*- FL
25	1		*RH TAILLAMP	Cut	462.40 FL	*462.40 FL
26	1		*REAR RH FENDER	Repair	1,842.40 FL	*- FL
27	1		*REAR RH FENDER 1/4 GLASS MOULDING	Not Necessary	208.70 FL	*- FL
28	1		*REAR RH FENDER LOWER WHEEL ARCH GARNISH	Serviceable	164.00 FL	*- FL
29	1		*SET REAR RH FENDER LOWER WHEEL ARCH GARNISH CLIPS	Not Necessary	40.00 FL	*- FL
30	1		*REAR RH FENDER UNDER SPLASH SHIELD	*Check	164.00 FL	*- FL
31	1		*SET REAR FENDER UNDER SPLASH SHIELD CLIPS	*Check	40.00 FL	*- FL
32	2		*REAR FENDER INNER SIDE TRIM BOARD	*Check	667.80 FL	*- FL
33	1		*SET REAR FENDER INNER SIDE TRIM BOARD CLIPS	*Check	80.00 FL	*- FL
34	1		*ROOF PANEL RH SIDE MOULDING	Serviceable	31.00 FL	*- FL
35	1		*REAR RH LOWER EXHAUST SILENCER	*Check	1,286.00 FL	*- FL
36	1		*REAR RH LOWER EXHAUST SILENCER TOP HEAT SHIELD	*Check	283.00 FL	*- FL
37	1		*SET REAR WINDSCREEN /REAR RH FENDER 1/4 GLASS SEALANT	Not Necessary	120.00 FS	*- FS
38	1		*REAR NUMBER PLATE	Dented	50.00 FS	*45.00 FS
39	1		*SET REAR END PANEL /SPARE TYRE PANEL SEALANT	*Check	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 14,173.90 5,601.20**- List Item Discount on L Items 20.00/20.00% (\$\$) 2,776.78 1,111.24**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
Total Parts (\$)						11,397.12	4,489.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE /REFIT ,PANEL BEAT AND REPLACEMENT OF DAMAGES (*Check)	New	1,800.00	0.00
2	TO PUTTY AND SPRAY SPRAY PAINTINGS CHARGES	New	1,400.00	1,200.00
3	TO REMOVE,REFIT REAR WINDSCREEN	New	140.00	120.00
4	TO REMOVE ,REFIT REAR RH FENDER 1/4 GLASS	New	100.00	0.00
5	TO CHECK WIRINGS AND LIGHTINGS	New	40.00	20.00
6	TO TRANSFER REAR TAILGATE FITTINGS	New	80.00	60.00
7	TO REMOVE,REFIT & RESET REVERSE SENSORS & REVERSE CAMERA	New	140.00	80.00
8	TO REMOVE,REFIT ROOF LINING ,REAR SEATS ASSY & UPHOLSTERY INODER TO FACILITATE REPAIR	New	180.00	100.00
9	TO REMOVE,REFIT REAR RH LOWER EXHAUST SILENCER	New	80.00	60.00
10	TO SUPPLY AND APPLY ANTI RUST TREATMENT (*Check)	New	100.00	0.00
Gross Labour Cost (S\$)			4,060.00	1,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >