

REF: SMC/23007338/KO

Kenneth

Vehicle: INT
Mr. Chai

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

७

1074

	Weekend (\$
1	100
2	100
3	100
4	100
5	100
6	100
7	100
8	100
9	100
10	100
11	100
12	100
13	100
14	100
15	100
16	100
17	100
18	100
19	100
20	100
21	100
22	100
23	100
24	100
25	100
26	100
27	100
28	100
29	100
30	100
31	100
32	100
33	100
34	100
35	100
36	100
37	100
38	100
39	100
40	100
41	100
42	100
43	100
44	100
45	100
46	100
47	100
48	100
49	100
50	100
51	100
52	100
53	100
54	100
55	100
56	100
57	100
58	100
59	100
60	100
61	100
62	100
63	100
64	100
65	100
66	100
67	100
68	100
69	100
70	100
71	100
72	100
73	100
74	100
75	100
76	100
77	100
78	100
79	100
80	100
81	100
82	100
83	100
84	100
85	100
86	100
87	100
88	100
89	100
90	100
91	100
92	100
93	100
94	100
95	100
96	100
97	100
98	100
99	100
100	100

DF MOTOR PTE LTD (202108068G)
32 SIN MING DRIVE 01-331
Sin Ming Industrial
SINGAPORE 575706
TEL :6453 9903
Email: dfmotor33@hotmail.com

Kenneth
96910663
"NOT Authored
11 Aug @
Recovery After Park
"
Kenneth Heng e/kkauto.com

ESTIMATED COST OF REPAIR

Estimated repair list for the accident motorcycle Yamaha Xmax Vehicle NO. FBS1862Z

S/No	Part No.	Description	Qty	Amount (SGD)
1)	1PA-F6246-10	END,GRIP <i>CH</i>	1.00	<i>Re</i> \$38.00 ✓
2)		STEERING COD	1.00	<i>"</i> \$180.00 ?
3)	B74-E4718-00	PROTECTOR,MUFFLER 1	1.00	<i>Re/CH</i> \$95.00 ✓
4)	B74-E5431-00	COVER,CRANKCASE 3	1.00	<i>CH</i> \$85.00 ✓
5)	B74-F1511-00	FRONT FENDER	1.00	<i>"</i> <i>Re</i> \$80.00 X
6)	B74-1513-00-P4	STAY, FENDER 1 <i>CH</i>	1.00	<i>CH</i> \$75.00 ✓
7)	B74-1514-00-P4	STAY,FENDER 2	1.00	<i>Re</i> \$75.00 X
8)	B74-F171L-00-P4	MOLE,SIDE COVER 3	1.00	<i>CH</i> \$65.00 ✓
9)	B74-F171M-00-P4	MOLE,SIDE COVER 4	1.00	<i>CH</i> \$65.00 ✓
10)	B74-F172A-00	PANEL 1 <i>CH</i>	1.00	<i>CH</i> \$65.00 ✓
11)	B74-F1731-00-P4	<i>Re</i> COVER,SIDE 3	1.00	<i>"</i> <i>CH</i> \$75.00 ✓
12)	B74-F1741-00-P4	<i>Re</i> COVER,SIDE 4	1.00	<i>CH</i> \$75.00 ✓
13)	B74-F3102-00	FRONT FORK ASSY (L.H)	1.00	\$395.00 ?
14)	B74-F3103-00	FRONT FORK ASSY (R.H)	1.00	\$395.00 ?
15)	B74-3340-00	UNDER BRAKET COMP.	1.00	<i>"</i> \$498.00 ?
16)	B74-F474W-00-P4	ASSIST,GRIP 2 <i>Re</i>	1.00	<i>Re</i> \$90.00 ✓
17)	B74-F6110-00	HANDLE COMP. <i>CH</i>	1.00	<i>Re</i> \$150.00 ✓
18)	B74-F6290-00	REAR VIEW MIRROR ASSY (RIGHT)	1.00	<i>Re</i> \$120.00 ✓
19)	B74-H2129-00	COVER,BATTERY	1.00	<i>CH</i> \$45.00 ✓
20)		FRONT SKRUR <i>1801</i>	4.00	<i>Re</i> \$35.00 ✓

DF MOTOR PTE LTD (202108068G)

32 SIN MING DRIVE 01-331

Sin Ming Industrial

SINGAPORE 575706

TEL :6453 9903

Email: dfmotor33@hotmail.com.sg**ESTIMATED COST OF REPAIR**

Estimated repair list for the accident motorcycle Yamaha Xmax Vehicle NO:FBS1862Z

S/No	Part No.	Description	Qty	Amount (SGD)
21)	B74-F7311-00	STAND.SIDE	1.00	<i>R</i> \$68.00 <i>X</i>
22)	B74-F7481-00	BOARD,FOOTREST	1.00	<i>607</i> 607 \$85.00 <i>✓</i>
23)	B74-7488-00	BOARD,FOOTREST 2	1.00	<i>" 607</i> \$85.00 <i>✓</i>
24)	B74-F8351-00-P4	BODY,COWLING	1.00	\$85.00 <i>?</i>
25)	B74-F835J-00-P2	BODY,FRONT UNDER 1	1.00	<i>" 607</i> \$90.00 <i>✓</i>
26)	B74-F835K-00-P2	BOBY,FRONT COVER 2 <i>114</i>	1.00	\$90.00 <i>?</i>
27)	B74-F8385-01	COVER,UNDER	1.00	\$80.00 <i>?</i>
28)	B74-F842A-00	COVER 5	1.00	\$45.00 <i>?</i>
29)	B74-F843C-00	COVER 6	1.00	\$48.00 <i>?</i>
30)	B74-H3310-00	FRONT FLAHER <i>Flasher</i> LIGHT ASSY 1	1.00	<i>607</i> \$75.00 <i>✓</i>
31)	B74-H3912-00	LEVER 1	1.00	<i>R</i> \$38.00 <i>✓</i>
32)	B74-H4300-00	HEADLIGHT ASSY	1.00	<i>607</i> \$595.00 <i>✓</i>
33)	B74-F7111-00	STAND MAIN <i>103</i>	1.00	<i>" R</i> \$118.00 <i>✓</i>
33)	LABOUR			\$550.00 <i>2801</i>

TOTAL: \$ 4753.00**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: