



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 9003L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOTLID	TO REPAIR SEE LABOUR	659.00	-
1	BOOTLID TOP LOCK	TO REPAIR SEE LABOUR	214.00	-
1	BOOTLID LOGO	NECESSARY	58.00	58.00
1	BOOTLID WEMBLEM 'VIOS'	NECESSARY	62.00	62.00
1	BOOTLID EMBLEM 'E'	NECESSARY	22.00	22.00
1	REAR BUMPER	DENTED / BUCKLED	591.00	556.00
1	REAR BUMPER TOW COVER	SERVICEABLE	38.00	-
2	REAR BUMPER SIDE RETAINER (FRONT) @\$98.00	SERVICEABLE	196.00	-
2	REAR BUMPER SIDE RETAINER (REAR) @\$55.00	SERVICEABLE	110.00	-
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	398.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	548.00	-
1	REAR END PANEL TOP GARNISH	SERVICEABLE	229.00	-
1	REAR FLOOR PANEL TOP BOARD	SERVICEABLE	135.00	-
	LESS 25% DISCOUNT		-815.00	-174.50
			2,445.00	523.50
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN)	SERVICEABLE	50.00	-
1	REAR BUMPER CLIP (SN)	NECESSARY	30.00	30.00
1	REVERSE SENSOR (SN)	DENTED	200.00	200.00
			280.00	230.00
<u>LABOUR</u>				
	SPRAY PAINTING ON AFFECTED AREAS .		600.00	400.00
	PANEL BEATING ON AFFECTED AREAS .INCLUSIVE OF THE REPAIR OF BOOTLID ,BOOTLID TOP LOCK,REAR BUMPER REINFORCEMENT AND REAR END PANEL.		800.00	200.00
	RESET TROUBLE CODE.	NOT NECESSARY	300.00	-
	REMOVE AND REFIT REAR UPHOLSTERY .	NOT NECESSARY	200.00	-
	TO CHECK ELECTRICAL WIRING.		80.00	15.00

Report Ref No. CS/AGI23007342/Kny3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY UNDERCOATING.	NOT NECESSARY	150.00	-
	APPLY ANTI RUST ON AFFECTED AREAS .	NOT NECESSARY	200.00	-
			2,330.00	615.00
GRAND TOTAL			5,055.00	1,368.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,100.00

Report Ref No. CS/AGI23007342/Kny3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.