



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Tan Say Yam Josiah	Cust No/Name	/Tan Say Yam Josiah
18, Ang Mo Kio Avenue 2	Reg No/Reg Date	SLQ9944K / 28/07/201
#14-32 The Panorama	Date In/Mileage	/ 108742
Singapore 567700	Chassis No	KNAHU815VH7177679
Contact No Mobile: 90904077	Engine No	D4FDHH102741
	Make/Model	KIA/CARENS 1.7 A D SX FL DY6
	Colour/Trim	9H BLACK CHERRY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	19/07/2023/ 20:01	BLE	261 / Edwin Caina	16328			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FR BUMPER & FR SUPPORT REPAIR BONNET , LHF FENDER & RHF FENDER								640 3200.00
E PNT98000 RESPRAY FR BUMPER , BONNET , LHF FENDER & RHF FENDER								550 2200.00
E PNT88000 REMOVE & REFIT AC COND & RADIATOR								200? 320.00
A 25000001 TOP UP & VACUUM AC GAS								? 80.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM								100.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								280.00
M SUNDRY SUPPLY FR NUMBER PLATE WITH CASING								60 80.00
E PNT88000 REMOVE & REFIT FR PARKING ASSIST SENSOR								80 100.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS								X 120.00
M SUNDRY SUPPLY BODY PNL SEALANT								X 80.00
M SUNDRY Sundries								20 50.00
M	EMBLEM-KIA				1.00	76.00	00.00	76.00
M	COVER-FR BUMPER				1.00	695.00	00.00	695.00
M	CAP-FRONT HOOK				1.00	3.00	00.00	3.00
M	BRACKET-FR BUMPER CTR,UPR				1.00	8.00	00.00	8.00
M	GRILLE ASSY-RADIATOR				1.00	471.00	00.00	471.00
M	STRIP ASSY-FR BUMPER UPR				1.00	38.00	00.00	38.00
M	COVER-RADIATOR GRILLE UPR				1.00	73.00	00.00	73.00
M	LIP-FRONT BUMPER				1.00	29.00	00.00	29.00
M	GRILLE-FRONT BUMPER				1.00	177.00	00.00	177.00
M	ABSORBER-FRONT BUMPER ENERGY				1.00	68.00	00.00	68.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Tan Say Yam Josiah	Cust No/Name /Tan Say Yam Josiah
18, Ang Mo Kio Avenue 2	Reg No/Reg Date SLQ9944K / 28/07/201
#14-32 The Panorama	Date In/Mileage / 108742
Singapore 567700	Chassis No KNAHU815VH7177679
Contact No Mobile: 90904077	Engine No D4FDHH102741
	Make/Model KIA/CARENS 1.7 A D SX FL DY6
	Colour/Trim 9H BLACK CHERRY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	19/07/2023/ 20:01	BLE	261 / Edwin Caina	16328
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M STIFFENER ASSY-FR BUMPER LWR		1.00	90.00	00.00	90.00
M RAIL ASSY-FR BUMPER ?		1.00	389.00	00.00	389.00
M BRACKET-FR BUMPER SIDE, LH		1.00	12.00	00.00	12.00
M BRACKET-FR BUMPER SIDE, RH		1.00	12.00	00.00	12.00
M COVER-FR BUMPER FOG LAMP, LH		1.00	78.00	00.00	78.00
M COVER-FR BUMPER FOG LAMP, RH		1.00	78.00	00.00	78.00
M LAMP ASSY-FRONT FOG, LH		1.00	206.00	00.00	206.00
M LAMP ASSY-FRONT FOG, RH		1.00	206.00	00.00	206.00
M WIRING HARNESS-FWS EXT		1.00	268.00	00.00	268.00
M ULTRASONIC SENSOR ASSY-P.A.S		4.00	162.00	00.00	648.00
M HOLDER-PARKING ASSIST SYSTEM		1.00	17.00	00.00	17.00
M HOLDER-PARKING ASSIST SYSTEM		1.00	17.00	00.00	17.00
M HOLDER-PARKING ASSIST SYSTEM		1.00	17.00	00.00	17.00
M HOLDER-PARKING ASSIST SYSTEM		1.00	17.00	00.00	17.00
M LAMP ASSY-HEAD, LH		1.00	1558.00	00.00	1558.00
M LAMP ASSY-HEAD, RH		1.00	1558.00	00.00	1558.00
M CARRIER ASSY-FRONT END MODULE		1.00	628.00	00.00	628.00
M COOLANT (4L) ?		1.00	26.00	00.00	26.00

Estimate

SURVEYOR NAME: RASU - H990010068SURVEYOR SIGNATURE: [Signature]DATE: 20/07/23REMARKS: 3 days

EXCESS: 800

Repair by paint. REVENT

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

8% GST on

Nett	14,073.00
14073.00	1125.84

Total Payable 15,198.84

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.