

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	STRIDES AUTOMO	OTIVE SERVICES PTE LTD		Ref:	CS3/SMR23007355/Rqy3e2
	60 WOODLANDS I E4SINGAPORE 75	NDUSTRIAL PARK 17705		Date:	27/07/2023
				Code:	SMR
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SMB 338L	Veh. Inspected	t	FBT 97S
	Policy No.		Coverage (\$)		0.00
	Claim No.	BUS/07/23/5027	Excess (\$)		0.00
	Assign From	HUA YEN	Assign Date		20/07/2023
2.	Vehicle Particulars & Condition				
	Make & Model	YAMAHA NMAX 155 ABS CVT	c.c		155
	Engine No.	HIDDEN	Year of Reg.		2021
	Chassis No.	MH3SG5680MK103829	Colour		GREY
	Odometer	-	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	FAIR			
3.	Conditions of Tyres				
		Size	Make		Balance
	R/H Front Tyre	110/70-18	PIRELLI		4 mm
	L/H Front Tyre				mm
	R/H Rear Tyre	130/70-18	PIRELLI		4 mm
	L/H Rear Tyre				mm
4.	Description of Damages				
	THE VEHICLE SUS	'EHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.			
5.	General Information				
	Accident Date	16/07/2023	Inspect Date /	Time	20/07/2023 ( 05:47 PM )
	Survey held at PRIMERO RACING				
	1 BUKIT BATOK CRESENT #04-34 WCEGA PLAZA SINGAPORE 658064				
5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				

Report Ref No. CS3/SMR23007355/Rqy3e2

Inspected By

**Automotive Assessor** 

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

DECD Astro Consultant CAE Library of August

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$