

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/III23005652/RVY3M4-1**Date:** 26/07/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MPC0003330_02
Claimant Vehicle No : SLW2098S **Insured Vehicle No :** SMM422T
 Date of Loss: 21/05/2023 Nature of Claim: TP Claim No: MPC2023D0005876

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLW2098S**
 Make & Model: TOYOTA CAMRY, 2.0 (A) Engine No: 6ARP043704
 Reg. Date: 02/10/2015 (Man. Year: 2015) Chassis No: MR053DK5100102822
 Colour: Black Odometer: 107231 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,782.80	2,381.26	4,401.54	64.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	620.00	730.00	54.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	8,132.80	3,001.26	5,131.54	63.10

INSPECTION

Date of Assignment: 20/07/2023
 Date Inspected: 05/06/2023 Inspected At: Hong San Hong Wei Pte Ltd (HQ)
 Blk 1002 Bukit Merah Lane 3 #01-85
 Singapore 159719
 Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Jul 2023)
Parts: 143	TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLW2098S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER	Repair	669.90 F	*- FL	
2	1		*FRONT BUMPER LOWER GRILLE	Cracked	875.60 F	*510.42 FL	
3	1		*N/S HEADLAMP	Broken	4,770.30 F	*2,397.93 FL	
4	1		*FRONT BUMPER SENSOR N/S	Jammed	387.00 FS	*200.00 FS	
5	1		*SET FRONT NO. PLATE W GARNISH	Not Necessary	80.00 FS	*- FS	
					Sub Total (S\$)	6,782.80	3,108.35
					- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	727.09
					Total Parts (S\$)	6,782.80	2,381.26

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE THE NECESSARY AFFECTED PARTS, STRAIGHTEN N/S HEADLAMP PANEL, REPAIR FRONT BUMPER AND REPLACE PARTS	New	800.00	300.00
2	PUTTY AND SPRAYPAINT ON ALL AFFECTED PARTS	New	400.00	250.00
3	REMOVE AND REFIT FRONT BUMPER SENSORS	New	100.00	40.00
4	REWIRE FRONT PORTION AND REFOCUS N/S HEADLAMP BEAM	New	50.00	30.00
			Gross Labour Cost (\$\$)	620.00
			1,350.00	620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >