

VERON

# PRECISION APPRAISAL SERVICES

Insurance Loss Assessors/ Adjusters Cargo Surveyors & Licensed Appraisers

227 Simei St 4 #06-42 Singapore 520227 Fax: 64444886 Company Registration No. 53139926E



## AUTOMOBILE INSPECTION REPORT

To:

**TAY HWA SENG**

**C/O Block 1001 Bukit Merah Lane 3  
#01-55 / #01 - 85 Singapore 159718**

### INSURANCE DETAILS

Insured : -  
Policy No. / Claim No. : -  
Sum Insured : -  
Excess Clause : -  
Windscreen Coverage : -  
Type of Claims : Third Party Claims  
Third Party Insurer : -  
Third Party Policy No. : -

### REFERENCE

Assigned By : As above  
Accident Date : 21 May 2023  
Assignment Date : 01 June 2023  
Inspection Date : 01 June 2023  
Our Reference No. : PAS/HSHW/230152/TP

Inspection Report Date : 12 June 2023

Workshop Name :  
**Hong San Hong Wei Pte Ltd**  
Inspection Address :  
**Block 1001 Bukit Merah Lane 3  
#01-55 / #01 - 85 Singapore 159718**

### PARTICULARS OF VEHICLE

Registration No. : SLW2098S	Mileage : 107231	Km/h
Make/Model : TOYOTA CAMRY 2.0 AUTO	Radio/Casette : Fitted	
Yr of Manuf/Regn : 02 Oct 2015	CD Disc Player : Fitted	
Carrying Capacity : 4seater	Air Conditioner : Fitted	
Chassis No. : MR053DK5100102822	Clock : Fitted	
Engine No. : 6ARP043704	Seat GBelt : Fitted	
Colour : Metallic Black	Wing Mirror : Fitted	
Class : Passenger( Private)	Other Accessories : Fitted	

### PRE-ACCIDENT CONDITION (Static Check Only)

Body Work : Good  
Paint Work : Good  
Handbrake : Serviceable  
Footbrake : Serviceable  
Steering : Serviceable  
Any Apparent :  
Eng Modifications : None

### VEHICLE VALUE

Market Value : -  
Wreck Value (Parf) : -

### TYRE SIZE & CONDITION

Front N/s Size : 215/60R16	80 %	Front O/s Size : 215/60R16	80 %
Make : MICHELIN		Make : MICHELIN	
Rear N/s size : 215/60R16	80 %	Rear O/s Size : 215/60R16	80 %
Make : MICHELIN		Make : MICHELIN	
Spare Size : 215/60R16	80 %	Spare Size :	
Make : MICHELIN		Make :	
		Jack & Tools : Intact/Missing	

Type of Wheel Rims: Alloy

Note: The above percentage % represent the estimated remaining tyre threads.

# PRECISION APPRAISAL SERVICES

Insurance Loss Assessors / Adjusters Cargo Surveyors & Licensed Appraisers



VEHICLE REGISTRATION NO. : SLW 2098 S

APPENDIX A


## POINT OF IMPACT

(Diagram A)

FRONT

Direction of impact/damage marked (→)(X)


The vehicle sustained impact on its N/s Front Portion (see Diagram D)



REAR

(Diagram B)


FRONT



REAR

(Diagram C)


FRONT



REAR

(Diagram D)

FRONT



REAR

## GENERAL DESCRIPTION OF DAMAGES

Parts damaged were: The front bumper and lower grille were dented.

## ADJUSTMENTS & RECOMMENDATIONS

A static inspection was carried out on 01/06/2023 & our report is here with enclosed for your perusal. The Repairs Estimate submitted by M/s HONG SAN HONG WEI PTE LTD as per attached Appraisal Schedule have been revised and scrutinised thoroughly by us & in our opinion, we consider it to be fair and reasonable. The repairer has agreed to effect repairs to the owners satisfaction & to roadworthy condition on an agreed Part-By-Part Repair Basis of \$5,487.87 after deducting the Policy Excess Clause of \$ NA. As instructed, we have not authorised any of the repairs on your behalf.

	Repairer's		Our	
	Estimate	Amount	Revised	Amount
Spares Parts	6782	80	4497	87
Towing Charges	X	X	X	X
PB Labour Charges	800	00	600	00
Others Misc Charges	150	00	90	00
Paintwork	400	00	300	00
Total	\$ 8132	80	\$ 5487	87

Under normal circumstances, the duration of repairs should not exceed Nine(09) days excluding Pre-Repair Inspection ( PRI ) / Pre - Repair Survey ( PRS ) waiting time frame.

Attached photographs taken during inspection Forty-Eight(48) Photographs.

## SPECIAL REMARKS

1. The inspection was conducted on a 'without prejudice' basis
2. On 06/05/2023, we examined the extent of damages.
3. On 07/06/2023, we examined the new replacement parts
4. On 09/06/2023, we examined the repaired vehicle

Yours Faithfully,



TF PHILIP FOO  
AIMI CAE, AMIMI  
AIAME, AMSAE-A  
Licensed Appraiser/Adjuster

Inspection Report Date: 12 June 2023

VEHICLE REGN NO : SLW 2098 S  
 OUR REFERENCE : PAS/HSHW/230152/TP  
 INSPECTION REPORT DATE : 12-Jun-23

**APPRAISEMENT SCHEDULE**

CONTINUATION SHEET NO : 1

S/No	Qty	Parts / Labour Descriptions	Remarks / Condition	Repairer's Estimate Amount \$ cts	Recommendation / Revised Amount \$ cts
<u>PARTS SUPPLY - LIST ITEMS</u>					
1	1pc	Front bumper	Badly Dented	669.90	Repair
2	1pc	Front bumper lower grille	Cracked 510.42	875.60	<del>733.20</del>
3	1pc	Front bumper sensor N/s	Jammed 200 S/N	387.00	<del>387.00</del>
4	1pc	N/s Headlamp	Broken 2397.93	4770.30	<del>4770.30</del>
				6702.80	5890.50
Less: 25% discount				2908.35 25% 2181.26	-
				6702.80	<u>4417.87</u>
<u>SPECIAL NETT ITEMS</u>					
1	1set	Front no. plate w garnish	Dented/Bent/Defaced	80.00	80.00 X
				6782.80	<u>4497.87</u>
<u>LABOUR &amp; MISC. CHARGES</u>					
1		Remove the necessary affected parts, straighten n/s headlamp panel, repair front bumper and replace parts		800.00	<del>600.00</del> 300
2		Putty and spraypaint on all affected parts		400.00	<del>300.00</del> 250
3		Remove and refit front bumper sensors		100.00	<del>60.00</del> 40
4		Rewire front portion and refocus n/s headlamp beam	620	50.00	30.00

2181.26  
620.00  
2001.00  
3001.26  
P/P

SUB / GRAND TOTAL 8132.80 5487.87  
 PRECISION APPRAISAL SERVICES

4 days

*Ce*  
