

RWAVE PTE LTD

CO REG. NO 201909822G EMAIL: RWAVEPTELTD@GMAIL.COM

50 BUKIT BATOK STREET 23  
#02-25 MIDVIEW BUILDING SINGAPORE 659578  
Contact: 9369 6861 / 9773 3456  
RE: Accident involving FW9487C

INVOICE

DATE: June 6, 2023  
INVOICE # FW9487C001  
FOR: FW9487C

DESCRIPTION	AMOUNT
LUMP SUM REPAIR (Inclusive of supplying parts and labour)	\$ 4,928.00
TOTAL	\$ 4,928.00

Make all checks payable to RWAVE PTE LTD  
If you have any questions concerning this invoice, contact James 93696861,  
rwavepteltd@gmail.com

RWAVE PTE LTD  
Reg. No 201909822G  
Issued by: James Ama

Motorcycle Appraisal Service Pte Ltd  
UEN: 202221186K  
Email: MotorcycleAppSvc@gmail.com  
Contact: 96724751

Our Ref : MAS/TP/2023-23  
Invoice Ref : MAS/TP/2023-23  
Vehicle No. : FW9487C  
Attn : RWAVE PTE LTD  
Company : RWAVE PTE LTD  
Address : Midview Building  
50 Bukit Batok Street 23  
#02-25  
Singapore 659578

**INVOICE**

\$

Surveyor Fee	550
Re-inspection Fee	120
Transportation Fee	80
Photographs ( @ \$1 per photo, total 37 photos)	37
Total	787

Yours Faithfully  
MOTORCYCLE APPRAISAL SERVICE



---

Jency Chua  
Automotive Appraisal

Motorcycle Appraisal Service Pte Ltd  
UEN: 202221186K  
Email: MotorcycleAppSvc@gmail.com  
Contact: 96724751

**ACCIDENT DAMAGED VEHICLE INSPECTION REPORT**

M/S	: RWAVE PTE LTD	Date	: 6/6/2023
	C/O RWAVE PTE LTD	Our Ref	: MAS/TP/2023-23
	Midview Building		
	50 Bukit Batok Street 23		
	#02-25 Singapore 659578		

**REFERENCE PARTICULARS**

Date of Accident	: 20 March 2023	Type of Inspection	: Third Party Claim
Date of Inspection	: 05 May 2023	Date of Re-Inspection	: 22 May 2023

**VEHICLE PARTICULARS**

Registration No.	: FW9487C	Engine No.	: 5PV-003423
Make	: YAMAHA	Chassis No.	: PMYSPV10000003423
Model	: RXZ	Odometer	: 67491
Year	: 2003	Colour	: Black & Silver

**CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)**

Engine Condition	: Working Condition	General Body Work	: Average
Foot Brake	: Serviceable	Steering	: Serviceable
Hand Brake	: Serviceable	Lightings	: Serviceable

**TYRE CONDITION (REMAINING ESTIMATED LIFE OF TYRE IN MM)**

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front side	: Dunlop	80/80-18	5mm
Rear side	: Dunlop	80/80-18	5mm

**GENERAL DESCRIPTION OF DAMAGES**

Damages were located all around the vehicle.

For more accurate details, please refer to the assessment for repairs and photographs attached.

**ASSESSMENT SUMMARY**

Our assessment of the repair costs to pre-accident condition was S\$4928 nett at a lump sum basis.  
(subject to GST if applicable)

Under normal circumstances, estimated period required for repairs is: Ten (10) working days.

Enclosed herewith the 37 photographs depicting damages to the vehicle.

Inspection conducted at: RWAVE PTE LTD  
50 Bukit Batok Street 23, Midview Building, #02-25, Singapore 659578

In accordance to your instruction, we have not authorized repairs and inspection was conducted strictly on a "**WITHOUT PREJUDICE BASIS**".

Contact: 96724751

Model : Yamaha RXZ

Our Ref. : MAS/TP/2023-23

## ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

### DESCRIPTION OF PARTS AND NATURE OF REPAIRS

[illegible]

S/N	SPECIAL NETT ITEMS	QUANTITY PC/SET	ASSESSED CONDITION	ORIGINAL QUOTATION (\$)	REVISED QUOTATION (\$)
1	Front license plate	1	re-do	60	50
<b>Total</b>				60	50

S/N	LABOUR CHARGES & MISC	QUANTITY PC/SET	ASSESSED CONDITION	ORIGINAL QUOTATION (\$)	REVISED QUOTATION (\$)
1	Replace, realign and adjust above damaged parts and check wiring and lightning system	1	necessary	1100	1000
2	To knock, straighten chassis and body balancing			NA	NA
3	To respray on accident affected area	1	necessary	550	500
4	Towing service	1	Necessary	150	120
5					
<b>Sub Total</b>				1800	1620
<b>Total</b>				5442	4928

#### **POINT OF IMPACT**

Vehicle was collided with another vehicle and rider was brought up to ambulance afterwards. It causes several damages all around the vehicle.

#### **ADJUSTMENT/ RECOMMENDATIONS**

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

#### **CONCLUSION**

The repairer has agreed to undertake repair the vehicle at a lump sum basis of S\$4928 nett corresponding to the replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours Faithfully  
MOTORCYCLE APPRAISAL SERVICE




---

Jency Chua  
Automotive Appraisal