

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/AIS23007394/KQP3E2  
**Date:** 01/08/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	
<b>Claimant Vehicle No :</b>	SFC936M	<b>Insured Vehicle No :</b>	SNK5278J
Date of Loss:	18/07/2023	Nature of Claim:	TP
		Claim No:	2023 32010860SL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SFC936M</b>	Engine No:	R18A3006839
Make & Model:	HONDA CROSSROAD, 1.8 (A)	Chassis No:	RT11005058
Reg. Date:	10/11/2007 (Man. Year: 2007)	Odometer:	203290 km
Colour:	Metallic Black		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R16	Rear Tyre Size:	225/55 R16
Front Left Side:	PETLAS 8 mm	Rear Left Side:	PETLAS 7 mm
Front Right Side:	PETLAS 8 mm	Rear Right Side:	PETLAS 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,849.00	1,178.40	670.60	36.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	980.00	600.00	380.00	38.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,829.00</b>	<b>1,778.40</b>	<b>1,050.60</b>	<b>37.14</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,400.00</b>		
<b>(S\$)</b>	2,829.00	1,400.00	1,429.00	50.51
<b>+ GST 8.00/8.00% (S\$)</b>	226.32	112.00	114.32	50.51
<b>Nett Amount (S\$)</b>	<b>3,055.32</b>	<b>1,512.00</b>	<b>1,543.32</b>	<b>50.51</b>

INSPECTION

Date of Assignment:	21/07/2023	Ready Autocare (HQ)
Date Inspected:	24/07/2023 Inspected At:	Blk 10 #03-06 AMK Auto Point, Ang Mo Kio Industrial Park 2 A, Ang Mo Kio Ave 5
Estimated Period of Repair:	3.0 days	Singapore 568047

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 01 Aug 2023)
<b>Parts:</b> M1-SUV	HONDA CROSSROAD 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SFC936M)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT RIGHT DOOR	Bent / Warped	1,250.00 F	*1,250.00 FL	
2	1		*FRONT RIGHT DOOR PROTECTOR	Dented	223.00 F	*223.00 FL	
3	1		*FRONT RIGHT SIDE SKIRT	Serviceable	376.00 F	*- FL	
					<b>Sub Total (\$)</b>	<b>1,849.00</b>	<b>1,473.00</b>
					<b>- List Item Discount on L Items 0.00/20.00% (\$)</b>	0.00	294.60
					<b>Total Parts (\$)</b>	<b>1,849.00</b>	<b>1,178.40</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ALL DAMAGED PARTS, KNOCK OUT DENTS, JACK OUT DAMAGED PANEL, ADJUST, REPLACE, RESHAPE, CUT, WELD, REFIX & REALIGN BODY STRUCTURE	New	500.00	300.00
2	SPRAY PAINTING FOR NEW AND REPAIR PARTS INCLUDING SUPPLY OF PAINTS MATERIALS	New	350.00	220.00
3	TO CHECK WIRING FOR PROPER FUNCTION	New	30.00	20.00
4	TO TRANSFER FRONT RIGHT COMPONENTS FROM OLD TO NEW	New	100.00	60.00
			<b>Gross Labour Cost (\$\$)</b>	<b>980.00</b>
				<b>600.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >