

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	HSBC LIFE (SING	APORE) PTE LTD	Ref:	CS3/HSB23007423/Tqp3e2	
	10 MARINA BOULI #48-01 MARINA BA 2SINGAPORE 018	AY FINANCIAL CENTRE TOWER	Date:	31/07/2023	
	ATTN: ANG YVON	NE	Code:	HSB	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 3113C	Veh. Inspected	FBN 7117D	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S3M04NSQ	Excess (\$)	0.00	
	Assign From	ANG YVONNE	Assign Date	21/07/2023	
2.	. Vehicle Particulars & Condition				
	Make & Model	YAMAHA YBR125	c.c	124	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	LBPRE1022J0010325	Colour	BLACK	
	Odometer	-	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	80/90 R18	GOLDEN BOY	5 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	80/90 R18	GOLDEN BOY	5 mm	
	L/H Rear Tyre			mm	
4.	4. Description of Damages				
	THE VEHICLE SUS BODY.	STAINED DAMAGES AT THE FRO			
5.	General Information				
	Accident Date	01/07/2023	Inspect Date / Time	25/07/2023 (02:30 PM)	
	Survey held at	TUNE IN MOTOR			
	BLK 1016 YISHUN INDUSTRIAL PARK A #01-214 SINGAPORE 768758				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				
	Report Ref No. CS3/HSR23007423/Tgn3e2				

Report Ref No. CS3/HSB23007423/Tqp3e2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser