

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/III23004837/RVY3M4-1**Date:** 03/08/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447\_02

**Claimant Vehicle No :** GBD8149H **Insured Vehicle No :** SMK6724T

Date of Loss: 08/05/2023 Nature of Claim: TP Claim No: MFL2023D0005251

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD8149H**

Make & Model: TOYOTA HIACE, 3.0 D DX DIESEL TURBO MT 2WD LGV (M) Engine No: 1KD2500400

Reg. Date: 28/05/2015 (Man. Year: 2015) Chassis No: KDH2015017065

Colour: Grey Odometer: 332031 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15C Rear Tyre Size: 195R15C

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,817.00	4,279.82	7,537.18	63.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,100.00	1,920.00	2,180.00	53.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,917.00</b>	<b>6,199.82</b>	<b>9,717.18</b>	<b>61.05</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,950.00</b>		
<b>Nett Amount (S\$)</b>	<b>15,917.00</b>	<b>4,950.00</b>	<b>10,967.00</b>	<b>68.90</b>

INSPECTION

Date of Assignment: 21/07/2023

Date Inspected: 11/05/2023 Inspected At:

RIDE NOW PRIVATE LIMITED  
1 BUKIT BATOK CRESCENT  
#04-40 WCEGA PLAZA SINGAPORE 658064

Estimated Period of Repair: 7.0 days

**Adjuster:** MOHD RASUL**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 03 Aug 2023)	
Parts:	N/A	TOYOTA HIACE 3.0 D DX DIESEL TURBO MT 2WD LGV (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD8149H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	673.10 FL	*598.60 FL
2	1		*REAR BUMPER LOWER BRACKET	Bent	192.00 FL	*25.00 FL
3	1		*REAR BUMPER SIDE RETAINER L/R @47/PCS 2PIECES	Torn (1Piece Only)	94.00 FL	*47.00 FL
4	1		*REAR END PANEL (INNER)	Dented	820.70 FL	*572.10 FL
5	1		*REAR END PANEL (OUTER)	Dented	743.00 FL	*642.00 FL
6	1		*REAR EXHAUST GASKET	Serviceable	48.30 FL	*- FL
7	1		*REAR EXHAUST PIPE	Repair	570.60 FL	*- FL
8	1		*REAR FLOOR PANEL	Repair	1,650.00 FL	*- FL
9	1		*REAR FLOOR PANEL CARPET	Serviceable	680.00 FL	*- FL
10	1		*REAR FLOOR PANEL TOP PLATE	Dented	195.00 FL	*195.00 FL
11	2		*REAR FLOOR PANEL TOP PLATE SIDE COVER L/R @88/PCS	Serviceable	176.00 FL	*- FL
12	1		*REAR MECHANISM LOCK COVER	Not Necessary	123.20 FL	*- FL
13	1		*REAR RH FENDER	Repair	1,546.90 FL	*- FL
14	1		*REAR SPARE TYRE BRACKET	Serviceable	311.00 FL	*- FL
15	1		*REAR SPARE TYRE CARRIER	Serviceable	65.00 FL	*- FL
16	1		*REAR SPARE TYRE SCREW	Serviceable	47.10 FL	*- FL
17	1		*REAR STEP PANEL	Dented	175.40 FL	*175.40 FL
18	1		*REAR TAILGATE	Dented	1,950.00 FL	*1,698.00 FL
19	1		*REAR TAILGATE LOGO EMBLEM	Necessary	63.00 FL	*63.00 FL
20	1		*REAR TAILGATE INNER TRIM BOARD	Serviceable	469.00 FL	*- FL
21	1		*REAR TAILGATE LOCK STRIKER	Serviceable	53.00 FL	*- FL
22	1		*REAR TAILGATE MECHANISM LOCK	Dented	264.00 FL	*264.00 FL
23	1		*REAR TAILGATE OUTER GARNISH	Serviceable	151.20 FL	*- FL
24	1		*REAR TAILGATE WEATHER STRIP	Kinded	391.00 FL	*288.00 FL
25	1		*REAR TAILGATE WINDSCREEN	Serviceable	1,498.50 FL	*- FL
26	1		*REAR TAILLAMP INNER QUARTER PANEL	Repair	295.00 FL	*- FL
27	1		*REAR TAILLAMP L/R @265/PCS 2PIECES	Grazed/Cracked (1Piece Only)	530.00 FL	*265.00 FL
28	2		*REAR TAILLAMP LOWER GARNISH L/R @157/PCS	Serviceable	314.00 FL	*- FL
29	2		*REAR TAILLAMP LOWER GARNISH RETAINER L/R @53/PCS	Not Necessary	106.00 FL	*- FL
30	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
31	1		*SET REAR BUMPER NUMBER PLATE (WITH FRAME)	Not Necessary	45.00 FS	*- FS
32	1		*SET REAR BUMPER REVERSE SENSOR	Necessary	280.00 FS	*200.00 FS
33	1		*SET REAR TAILGATE 70KM STICKER	Necessary	25.00 FS	*15.00 FS
34	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
35	1		*REAR TAILGATE WINDSCREEN SEAL }	Dented	60.00 FS	*60.00 FS
36	1		*SET REAR TAILGATE WINDSCREEN SEALANT }	Dented	80.00 FS	*- FS
37	1		*REAR TAILGATE INNER METAL BOARD	Dented	500.00 FS	*300.00 FS
38	1		*SET REAR TAILLAMP CLIPS L/R	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

	Sub Total (\$\$)	15,366.00	5,488.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,549.00	1,208.28	

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					<b>Total Parts (S\$)</b>	<b>11,817.00      4,279.82</b>
Report was unsubmitted during this print-out.						

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING SYSTEM	New	50.00	30.00
2	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	200.00	0.00
3	TO R&R REAR WINDSCREEN GLASS	New	200.00	120.00
4	TO R&R TAILGATE ATTACHMENTS	New	150.00	50.00
5	TO R&R REAR EXHAUST PIPE	New	150.00	0.00
6	TO R&R REAR TRIMMING AND PARTITION FOR HOT WORK REPAIR	New	200.00	60.00
7	TO CUT AND WEILD ON REAR END PANEL INNER AND OUTER. TO PANEL BEAT ON R FLOOR BOARD. TO R&R TAILLAMP, REAR BUMPER, TAILGATE AND OTHERS ATTACHMENTS	New	1,500.00	800.00
8	TO RESPRAY ON TAILGATE,REAR BOTH FENDERS, REAR END PANEL, FLOOR BOARD AND ACCIDENT AFFECTED AREA	New	1,500.00	800.00
9	TO CARRY OUT BODY CAVITY PRESERVATION	New	150.00	60.00
<b>Gross Labour Cost (S\$)</b>			<b>4,100.00</b>	<b>1,920.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >