

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG23007485/UNY3E2**Date:** 04/08/2023REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 30002649169

Claimant Vehicle No : JQX5641**Insured Vehicle No :** SNC5842Y

Date of Loss: 06/03/2023

Nature of Claim: TP

Claim No: 305872

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **JQX5641**

Make & Model: YAMAHA 135LC, 135cc

Engine No: G399E302991

Reg. Date: 06/07/2015 (Man. Year: 2015)

Chassis No: PMYUG0410F0302991

Colour: Red

Odometer: 84197 km

Engine Capacity: 135 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70-90-17

Rear Tyre Size: 80-90-17

Front Left Side: Maxxis 5 mm

Rear Left Side: Maxxis 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,776.10	3,850.70	1,925.40	33.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	980.00	300.00	680.00	69.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,756.10	4,150.70	2,605.40	38.56
Approved Total (Overridden) (S\$)		3,300.00		
Nett Amount (S\$)	6,756.10	3,300.00	3,456.10	51.16

INSPECTION

Date of Assignment: 24/07/2023

Date Inspected: 25/07/2023 Inspected At:

Erofia Motor Trading Pte Ltd (KAKI BUKIT)

1 KAKI BUKIT AVE 6 #02-62

Singapore 417883

Estimated Period of Repair: 0.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MV:RM 5000.00 (Est)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Aug 2023)	
Parts:	N/A	YAMAHA 135LC 135cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JQX5641)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT FORK TUBE ASSY	Bent / Cracked	640.00 FL	*640.00 FL
2	1		*FORK UNDER BRACKET	Bent	185.00 FL	*185.00 FL
3	1		*FRONT WHEEL RIM	Cracked / Warped	380.00 FL	*380.00 FL
4	1		*FRONT RIM SHAFT	Bent	45.00 FL	*45.00 FL
5	1		*FRONT RIM BEARING	Necessary	38.00 FL	*38.00 FL
6	1		*FRONT BRAKE DISC	Not Necessary	185.00 FL	*- FL
7	1		*HANDLE BAR	Bent	88.00 FL	*88.00 FL
8	1		*SET HANDLE-BAR ENDS	Cut	74.00 FL	*74.00 FL
9	1		*SET HAND GRIP	Torn	55.00 FL	*55.00 FL
10	1		*HANDLE BAR INNER BRACKET	Cracked / Bent	78.00 FL	*78.00 FL
11	1		*HEADLAMP ASSY	Cracked	485.00 FL	*485.00 FL
12	1		*SET SIDE MIRRORS	Cut / Broken	110.00 FL	*110.00 FL
13	1		*SET FRONT SIGNALS	Cracked	140.00 FL	*140.00 FL
14	1		*FRONT SIGNAL LOWER GARNISH	Cracked	105.00 FL	*105.00 FL
15	1		*SET FAIRING ASSY	Cracked	525.00 FL	*525.00 FL
16	1		*RADIATOR	Dented / Punctured	580.00 FL	*580.00 FL
17	1		*EXHAUST ASSY	Repair	685.00 FL	*- FL
18	1		*EXHAUST END CAP	Not Necessary	75.00 FL	*- FL
19	1		*EXHAUST PROTECTOR	Not Necessary	55.00 FL	*- FL
20	1		*BASKET	Cracked	135.00 FL	*135.00 FL
21	1		*SET SIDE LOWER COVER - MATT	N/S Cracked	160.00 FL	*160.00 FL
22	1		*FRONT FOOTREST BRACKET	Bent	65.00 FL	*65.00 FL
23	1		*FRONT FOOTREST RUBBERS	O/S Torn	70.00 FL	*35.00 FL
24	1		*BRAKE PEDAL	Repair	125.00 FL	*- FL
25	2		*REAR FOOTRESTS	Not Necessary	80.00 FL	*- FL
26	1		*REAR FOOTREST BRACKETS	Not Necessary	156.00 FL	*- FL
27	1		*SET NUMBER PLATE	Necessary	38.00 FS	*10.00 FS
28	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
29	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
30	1		*SET STEERING CONE	Necessary	185.00 FS	*50.00 FS
31	1		*SET STICKER	Necessary	120.00 FS	*60.00 FS
32	1		*REAR BOX	Cut	380.00 FS	*200.00 FS
33	1		*REAR BOX BRACKET	Not Necessary	180.00 FS	*- FS
					Sub Total (\$\$)	6,308.00 4,243.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	531.90 392.30
					Total Parts (\$\$)	5,776.10 3,850.70

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
2	TO PROVIDE LABOUR	New	480.00	300.00
3	TO RE-ALIGN BODY FRAME	New	420.00	0.00
Gross Labour Cost (\$)			980.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >