# Note: This document has not been finalised.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park Singapore 408933

Attn: Melvin Ye Yongkang Date: 26 Jul 2023

### **Preliminary Advice**

Insured Vehicle No : SNC5842Y

TP Vehicle No : JQX5641 Accident Date : 06/03/2023

Make : TOYOTA HARRIER Assignment Date : 24/07/2023

Date of Inspection : 25/07/2023 Est. Duration of Repair : 4

Inspection At : EROFIA MOTOR TRADING PTE LTD (KAKI BUKIT)

1 KAKI BUKIT AVE 6 #02-62 SINGAPORE 417883

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,756.10
Revised Amount	:S\$	4,150.70
Check Items (Estimated)	:S\$	462.00
Total	:S\$	4,612.70

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$ 5,000.00 (RM)

COE / PARF Rebate :S\$
Salvage Value :S\$
Margin for Repair :S\$

#### Remarks

(		)	The vehicle is economical for repair
(		)	The vehicle is not economical for repair
(		)	Part-by-Part repair
(	Χ	)	Lump Sum repair

(X) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.