

Your Ref : 305872

Date: 04th Aug 2023

Our Ref : CS/MSG23007485/Uny3e2

M/s MSIG Insurance (S) Pte Ltd

4 Shenton Way #21-01

SGX Centre 2

Singapore 068807

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE JQX 5641
INSURED VEHICLE: SNC 5842Y
ACCIDENT ON 06/03/2023**

Instruction was received to inspect the vehicle Reg. No. JQX 5641. The inspection was conducted on 25/07/2023 at the premises of M/s Erofia Motor Trading Pte Ltd, 1 Kaki Bukit Avenue 6 #02-62, Singapore 417883.

The following vehicle information was recorded:

Registration Number	: JQX 5641
Make/Model	: Yamaha 135LC
Year of Registration	: 2015
Body Colour	: Red
Chassis Number	: PMYUG0410F0302991
Engine Capacity	: 135 cc
Speedometer Reading	: 84197 km

The vehicle sustained damages at the front portion and o/s body. The Estimated repair cost of such vehicle is S\$3,300.00 (Sin Dollars: Three Thousand and Three Hundred only.) (Details see photographs enclosed)

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as **"Total Loss"**.

Market Value S\$ RM 5,000.00 (est)

Vehicle Inspected By:

Ch

CHUA KANG SENG
Licensed Appraiser

the

K.K.LAU
*MSc(Eng M), B Eng(Hons), PEng(UK),
 MASME(USA), B Bus(Aust), MBA(UK),
 IEng(UK), MIIE(mech), MinstAEA, MFIEA,
 MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
 AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
 Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.