

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI23007487/TNY3E2**Date:** 31/07/2023REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MN000847

Claimant Vehicle No : SHD7133M**Insured Vehicle No :** SNF4196U

Date of Loss: 23/07/2023

Nature of Claim: TP Claim No: M2304244

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHD7133M**

Make & Model: HYUNDAI I40, 1.7 D CRDi (A)

Engine No: D4DFDU579589

Reg. Date: 10/11/2016 (Man. Year: 2016)

Chassis No: KMHLB41UMHU096283

Colour: Blue

Odometer: 911695 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: West Lake 6 mm

Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,098.36	2,080.76	17.60	0.84
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	650.00	530.00	120.00	18.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,759.36	2,621.76	137.60	4.99
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	2,759.36	2,100.00	659.36	23.90
+ GST 8.00/8.00% (S\$)	220.75	168.00	52.75	23.90
Nett Amount (S\$)	2,980.11	2,268.00	712.11	23.90

INSPECTION

Date of Assignment:	24/07/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	25/07/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang)
			59 Loyang Drive
			Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Jul 2023)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD7133M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER ASSY	Deformed	1,052.20 FL	*1,052.20 FL
2	10		*FRT BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
3	1		*FRT RADIATOR GRILLE	Cracked	1,480.00 FL	*1,480.00 FL
4	1		*FRT NUMBER PLATE	Cut	55.00 F	*55.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,609.20	2,587.20
- List Item Discount on L Items 20.00/20.00% (S\$)	510.84	506.44
Total Parts (S\$)	2,098.36	2,080.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	300.00	280.00
2	SPRAYPAINT	New	300.00	250.00
3	CHECK WIRING	New	50.00	0.00
Gross Labour Cost (\$\$)			650.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >