

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	ICE BHD	Re	ef:	CS3/LPC23007496/Kqy3e2	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Da	ate:	28/07/2023	
			Co	ode:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBG 7282X	Veh. Inspected		GBK 2657K	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	22/23/23/VC05/027639	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		20/07/2023	
2. Vehicle Particulars & Condition						
	Make & Model	NISSAN NV200 (M)	c.c		1461	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	VSKYBAM20Z0179879	Colour		MULTI COLOUR	
	Odometer	89353 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	185/70 R14	FIRENZA		6 mm	
	L/H Front Tyre	185/70 R14	FIRENZA		6 mm	
	R/H Rear Tyre	185/70 R14	DUNLOP		5 mm	
	L/H Rear Tyre	185/70 R14	DUNLOP		5 mm	
4. Description of Damages						
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR O/S PORTION.				
5.	General Information					
	Accident Date	01/07/2023	Inspect Date / Tim	ne	25/07/2023 (10:17 AM)	
_	Survey held at	TOH MOTOR ENTERPRISE				
		160 SIN MING DRIVE #05-16 SIN MING AUTOCITY SINGAPORE 575722				
5a. Remarks						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC23007496/Kqy3e2

Inspected By

KONG SENG CHEONG

Licensed Appraiser

Tu

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser