

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |  |   |                 |                          |  |
|---|--|---|-----------------|--------------------------|--|
|   | LONPAC INSURAN   | NCE BHD                                 | Ref:            | CS3/LPC22008802/Dcy3e2-1 |  |
|   | 300 BEACH ROAD<br>#17-04/07 THE CO   | NCOURSESINGAPORE 199555                 | Date:           | 31/07/2023               |  |
|   |  |   | Code:           | LPC2                     |  |
| 1.  | Policy Particulars :- THIRD PARTY CLAIM  |   |                 |                          |  |
|   | Insured Veh.   | YN 3653B                                | Veh. Inspected  | SMP 9794U                |  |
|   | Policy No.   |   | Coverage (\$)   | 0.00                     |  |
|   | Claim No.  | 22/22/22/VC05/026263                    | Excess (\$)     | 0.00                     |  |
|   | Assign From  | HUEY NI                                 | Assign Date     | 22/07/2023               |  |
| 2. Vehicle Particulars & Condition                                |  |   |                 |                          |  |
|   | Make & Model   | KIA CERATO 1.6                          | c.c             | 1591                     |  |
|   | Engine No.   | HIDDEN                                  | Year of Reg.    | 2019                     |  |
|   | Chassis No.  | KNAF1416MK5052280                       | Colour          | GREY                     |  |
|   | Odometer   | 78106 KM                                | Steering        | IN ORDER                 |  |
|   | Brakes   | IN ORDER                                | Modification    | STANDARD ALLOY RIM       |  |
|   | General  | GOOD                                    |                 |                          |  |
| 3.  | 3. Conditions of Tyres   |   |                 |                          |  |
|   |  | Size                                    | Make            | Balance                  |  |
|   | R/H Front Tyre   | 195/65 R15                              | NEXEN           | 6 mm                     |  |
|   | L/H Front Tyre   | 195/65 R15                              | NEXEN           | 6 mm                     |  |
|   | R/H Rear Tyre  | 195/65 R15                              | NEXEN           | 6 mm                     |  |
|   | L/H Rear Tyre  | 195/65 R15                              | NEXEN           | 6 mm                     |  |
| 4.  |  |   |                 |                          |  |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.  |   |                 |                          |  |
|   | DAMAGES SEE DETAILS.   |   |                 |                          |  |
| 5.  | General Information  |   |                 |                          |  |
|   | Accident Date  | 07/09/2022                              | Inspection Date | 07/09/2022               |  |
|   | Survey held at   | y held at D'S GRAFFITI CONCEPTS PTE LTD |                 |                          |  |
|   | 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875   |   |                 |                          |  |
| 5a.   | Remarks  |   |                 |                          |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                 |                          |  |
| 5b.   | Estimate Days of Repair  |   |                 |                          |  |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days  |   |                 |                          |  |
|   | •  |   | ·               |                          |  |