



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJQ 7067D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED / HOLDER BROKEN	1,225.00	1,151.00
1	FRONT BUMPER SIDE RETAINER RH	CRACKED	48.00	48.00
1	HEAD LAMP RH	CRACKED	779.60	779.60
1	HEAD LAMP LOWER BRACKET RH	CRACKED	72.50	72.50
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	645.00	-
1	FRONT FENDER INNER SHIELD RH	SERVICEABLE	157.00	-
	LESS 20% DISCOUNT		-585.42	-410.22
			2,341.68	1,640.88
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NOT NECESSARY	40.00	-
			90.00	50.00
	<u>LABOUR</u>			
	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		600.00	300.00
	TO PUTTY & SPRAY PAINT ACCIDENT DAMAGED PARTS AND ADJACENT PANELS.		600.00	400.00
	TO APPLY RUST PROOFING ON ACCIDENT DAMAGED PARTS AND ADJACENT PANELS.	NOT NECESSARY	40.00	-
	WIRING /BULB CHECKING/FOCUSING.		40.00	20.00
			1,280.00	720.00
	GRAND TOTAL		3,711.68	2,410.88
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,900.00

Report Ref No. CS3/SMR23000142/Kny3m4-1

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.