



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CS3/SMR23000142/Kny3-1

STRIDES AUTOMOTIVE SERVICES PTE LTD
60 WOODLANDS INDUSTRIAL PARK
E4SINGAPORE 757705

Ref: ~~CS3/SMR23000142/Kny3-1~~

Date: ~~12/01/2023~~ 25/07/2023

Code: SMR

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHB 5123R	Veh. Inspected	SJQ 7067D
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/12/22/2082	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	05/01/2023 25/07/2023

2. Vehicle Particulars & Condition

Make & Model	HONDA AIRWAVE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	GJ11304060	Colour	METALLIC GREY
Odometer	243783 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/65 R15	DUNLOP	8 mm
L/H Front Tyre	175/65 R15	DUNLOP	8 mm
R/H Rear Tyre	175/65 R15	DUNLOP	8 mm
L/H Rear Tyre	175/65 R15	DUNLOP	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.

5. General Information

Accident Date	31/12/2022	Inspection Date	09/01/2023
Survey held at	YAP MOTOR SERVICE PTE LTD BLK 7 SIN MING IND EST SEC C #01-80 & 82 SINGAPORE 575642		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------