

**COZON ENGINEERS**

Blk 206A Compassvale Lane #02-77 Singapore 541206  
 UEN: 53206579D

**ACCIDENT VEHICLE DAMAGE ASSESSMENT REPORT**

Our reference no.: 23-20035

Date: 28/04/2023

**DESCRIPTION / IDENTIFICATION OF VEHICLE****"Without Prejudice"**

Registration No:	SJQ7067D	Make:	Honda
Register Owner:	Chan Chee Kin	Model:	AIRWAVE
Chassis Number:	GJ11304060	Transmission:	Auto
Colour:	Grey	Odometer:	243783km

**STATIC CHECK**

Steering:	In order	Paintwork:	Good
Handbrake:	In order	General Condition:	Good
Foot Brake:	In order		

**CONDITION OF TYRES**


Front Tyre Size:	175/65R15		
Front Left Side:	85% Dunlop	Front Right Side:	85% Dunlop
Rear Tyre Size:	175/65R15		
Rear Left Side:	85% Dunlop	Rear Right Side:	85% Dunlop

**INSPECTION**

Date of inspection:	9/1/2023	Date of Accident:	31/12/2022
---------------------	----------	-------------------	------------

**AREA & DIRECTION OF IMPACT**

Enclosed photographs for more detail of the damages.



In view of the age of the said vehicle and with my professional opinion, the repair cost recommended at  
 with number of working days for repair estimated at

**\$3,000.00**

\* 3 days

**Tan LL** (Automotive Appraiser)  
 NTC-3 (Motor Vehicle Mechanic)  
 NTC-2 (Automotive Technology)  
 Certificate from Vocational Institute (Anti-skid Brake System)  
 Trainer of Institute of the Motor Industry, UK  
 Enterprise Singapore - Recognised Certification for Management Consultants

# COZON ENGINEERS

Blk 206A Compassvale Lane #02-77 Singapore 541206  
UEN: 53206579D

Our reference no.: 23-20035

Date: 28/04/2023

## Parts Assessment

Parts Description	Qty	Condition	Workshop's Estimate	Our Adjustment
<u>List Items:</u>				
Front bumper 1151	1	deformed,holder broken	1225.00	1225.00
Front bumper side retainer rh	1	cracked	48.00	48.00
Head lamp rh	1	cracked	779.60	779.60
Head lamp lower bracket rh	1	cracked	72.50	72.50
Front fender rh	1	buckled	645.00	645.00 X
Front fender inner shield rh	1	torn	157.00	157.00 X
<b>Sub- Total</b>			2927.10	2927.10
Parts discount : 20%			585.42	585.42
<b>Sub-Total costs for parts</b>			<b>2341.68</b>	<b>2341.68</b>

## Special Nett Items:

Front bumper clips	set	necessary	50.00	50.00
Front fender inner shield clip	set	necessary	40.00	40.00 X
<b>Sub-Total cost for parts</b>			<b>90.00</b>	<b>90.00</b>
<b>Total cost for parts</b>			<b>2431.68</b>	<b>2431.68</b>

# COZON ENGINEERS

Blk 206A Compassvale Lane #02-77 Singapore 541206  
UEN: 53206579D

Our reference no.: 23-20035

Date: 28/04/2023

## Labour Assessment

Description	Workshop's Estimate	Our Adjustment
To dismantle, replace, cut, weld, knock out dents to straighten accident damaged parts	600.00	500.00 300/
To putty & spray paint accident damaged parts and adjacent panels	600.00	500.00 400/
To apply rust proofing on accident damaged parts and adjacent panels	40.00	25.00 X
Wiring /bulb checking/focusing	40.00	30.00 20
<b>Total cost for Labour</b>	<b>1,280.00</b>	<b>1,055.00</b>

## Adjusted Repair Cost

<b>Total cost for Parts</b>	<b>2,431.68</b>	
<b>Lump Sum discount : 20%</b>	<b>486.34</b>	
	<b>1,945.34</b>	<b>A</b>
<b>Total cost for Labour</b>	<b>1,055.00</b>	<b>B</b>
<b>Total cost for Parts &amp; Labour (Round off)</b>	<b>3,000.00</b>	<b>A+B</b>

The recommended cost of repairs based on lump sum repairs is : \$3,000.00  
and the recommended number of working days for the repair is : 4