

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/III22009958/DVY3E2-1**Date:** 28/07/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0006372\_01  
**Claimant Vehicle No :** SLW4210X **Insured Vehicle No :** SHD2487A  
 Date of Loss: 07/10/2022 Nature of Claim: TP Claim No: MFL2022D0005773

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLW4210X**  
 Make & Model: HYUNDAI ELANTRA, 1.6 AD GLS (AMS) (A) Engine No: G4FGJU133898  
 Reg. Date: 12/02/2018 (Man. Year: 2018) Chassis No: KMHD841CMJU627148  
 Colour: Red Odometer: 99172 km  
 Engine Capacity: 1591 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
 Front Left Side: Pirelli 6 mm Rear Left Side: Yokohama 5 mm  
 Front Right Side: Pirelli 6 mm Rear Right Side: Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,506.10	2,504.40	5,001.70	66.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,500.00	1,540.00	1,960.00	56.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,006.10</b>	<b>4,044.40</b>	<b>6,961.70</b>	<b>63.25</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,250.00</b>		
<b>Nett Amount (S\$)</b>	<b>11,006.10</b>	<b>3,250.00</b>	<b>7,756.10</b>	<b>70.47</b>

INSPECTION

Date of Assignment: 25/07/2023  
 Date Inspected: 18/10/2022 Inspected At: Zolar Auto (HQ)  
 1 Kaki Bukit Ave 6, #02-42 Autobay @ Kaki Bukit  
 Singapore 417883  
 Estimated Period of Repair: 4.0 days

**Adjuster:** BRYAN TANI**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jul 2023)
<b>Parts:</b>	143	HYUNDAI ELANTRA 1.6 AD GLS (AMS) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLW4210X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER O/S	Repair	845.20 F	*- FL
2	1		*FRONT DOOR O/S	Dented	1,362.20 F	*1,362.20 FL
3	1		*SET FRONT DOOR BLACK TAPE O/S	Necessary	177.60 F	*60.00 FL
4	1		*FRONT DOOR WEATHERSTRIP OUTER O/S	Not Necessary	285.10 F	*- FL
5	1		*FRONT DOOR WEATHERSTRIP INNER O/S	Not Necessary	172.30 F	*- FL
6	1		*FRONT DOOR GLASS RUN CHANNEL O/S	Not Necessary	177.80 F	*- FL
7	1		*FRONT DOOR REGULATOR ASSY O/S	Not Necessary	483.00 F	*- FL
8	1		*FRONT DOOR INNER LOCK O/S	Distorted	371.70 F	*297.00 FL
9	1		*REAR DOOR O/S	Dented	1,238.80 F	*1,238.80 FL
10	1		*REAR DOOR WEATHERSTRIP OUTER O/S	Not Necessary	285.10 F	*- FL
11	1		*REAR DOOR WEATHERSTRIP INNER O/S	Not Necessary	153.20 F	*- FL
12	1		*SET REAR DOOR BLACK TAPE O/S	Necessary	177.60 F	*60.00 FL
13	1		*REAR DOOR GLASS RUN CHANNEL O/S	Not Necessary	152.90 F	*- FL
14	1		*REAR FENDER O/S	Repair	943.60 F	*- FL
15	1		*REAR BUMPER (NPA)	Repair	0.00 F	*- FL
16	1		*SUNDRIES	Necessary	40.00 FS	*30.00 FS
17	1		*FRONT DOOR SEALANT O/S	Necessary	100.00 FS	*30.00 FS
18	1		*SET FRONT DOOR TRIMBOARD CLIPS O/S	Not Necessary	50.00 FS	*- FS
19	1		*REAR DOOR SEALANT O/S	Necessary	100.00 FS	*30.00 FS
20	1		*SET REAR DOOR TRIMBOARD CLIPS O/S	Not Necessary	50.00 FS	*- FS
21	1		*SET REAR BUMPER CLIPS	Not Necessary	60.00 FS	*- FS
22	1		*REAR TYRE O/S	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,506.10</b>	<b>3,108.00</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	<b>0.00</b>	<b>603.60</b>
<b>Total Parts (\$\$)</b>	<b>7,506.10</b>	<b>2,504.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	1,200.00	400.00
2	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS	New	80.00	30.00
3	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	80.00
4	TO APPLY UNDERCOATING ON THE ACCIDENT REPAIR AND REPLACED PANEL FOR RUST PROTECTION	New	200.00	30.00
5	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY O/S FRONT FENDER, FRONT DOOR, REAR DOOR, REAR FENDER, REAR BUMPER AND OTHER AFFECTED AREA / PANEL	New	1,800.00	1,000.00
6	TO REMOVE AND REFIT O/S REAR TYRE TO REPLACE. TO PERFORM TYRE BALANCING	New	100.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>3,500.00</b>	<b>1,540.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >