

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581) Email: motor@wahhong.sg

(199806235M)

Vehicle No. GBK8840H TOYOTA DYNA 150T

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and	800.00	
2	components To supply paint materials, expandable items & putty, respray paint on	1000.00	
3	parts replaced & repaired To remove & refix wiring system at accident damaged area and check	90.00	
4	for all electrical proper function To perform anti-rust treatment on affected areas	90.00	
5	To remove, replace and focus headlamp	60.00	
	Labour Total :	2040.00	
	TOTAL (PARTS & LABOUR):	7266.50	