

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
	LONPAC INSURAN	NCE BHD	Ref:	CS3/LPC23007628/Kvy3e2
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Date:	03/08/2023
			Code:	LPC2
1.	Policy Particulars :- (THIRD PARTY CLAIM)			
	Insured Veh.	YN 7317X	Veh. Inspected	SFU 2959P
	Policy No.		Coverage (\$)	0.00
	Claim No.	22/23/23/VC05/027771	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	27/07/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA VIOS (A)	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	MR053HY9305086510	Colour	WHITE
	Odometer	223552 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/50 R15	TOURADOR	5 mm
	L/H Front Tyre	195/50 R15	TOURADOR	5 mm
	R/H Rear Tyre	195/50 R15	TOURADOR	7 mm
	L/H Rear Tyre	195/50 R15	TOURADOR	7 mm
4. Description of Damages				
	THE VEHICLE SUS PORTION.	STAINED DAMAGES AT THE FR		
5.	General Information			
	Accident Date	25/07/2023	Inspect Date / Time	28/07/2023 (10:20 AM)
	Survey held at	AABE SERVICES		
	BLK 5034 ANG MO KIO INDUSTRIAL PARK 2 #01-329 SINGAPORE 569537			
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/LPC23007628/Kvy3e2

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser