

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMP 2568C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (WCP)	BROKEN	2,073.00	2,073.00
10	FRONT BUMPER CLIPS @\$2.00 (WCP)	NECESSARY	20.00	20.00
1	FRONT FENDER RH (WCP)	DENTED	1,440.00	1,440.00
1	FRONT FENDER COVER RH (WCP)	BROKEN	267.00	267.00
6	FRONT FENDER COVER NUTS @\$1.50 (WCP)	NECESSARY	9.00	9.00
1	FRONT FENDER LAMP (WCP)	CUT	146.00	146.00
	COST PLUS 20%		791.00	791.00
			4,746.00	4,746.00
	SPECIAL NETT ITEMS			
1	DOOR STICKER (SN)	NECESSARY	70.00	70.00
			70.00	70.00
	<u>LABOUR</u>			
	LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.		600.00	600.00
	TO PUTTY AND RESPRAY FRONT BUMPER, RHF FENDER, RH DOOR, AND AFFECTED AREA.		600.00	600.00
	TO CHECK WIRING AND UPDATE SYSTEM.		100.00	100.00
	TO APPLY TUFF COATING.		120.00	30.00
	TO DEACTIVATE AND ACTIVE EV HIGH VOLTAGE BATTERY AS SAFETY PRECAUTION (EV REPAIR PROTOCOL BY LTA).		150.00	100.00
	TO CARRY OUT DIAGNOSTIC SCAN TEST AND UPDATE SYSTEM UPON COMPLETION OF COLLISION REPAIRS.		200.00	150.00
			1,770.00	1,580.00
	GRAND TOTAL		6,586.00	6,396.00



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	5,100.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS1/LPC23007660/Dvy3m4



Automotive Assessor / Investigator