8/1/23, 9:51 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III22007072/DCY3M4-1

01/08/2023 Date:

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_02

Claimant Vehicle SMS7124B Insured Vehicle No: GBH8173R

No:

Date of Loss: 22/07/2022 Nature of Claim: Claim No: MFL2022D0003942

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMS7124B

HYUNDAI AD AVANTE, 1.6 GLS S (A) G4FGKU014395 Make & Model: Engine No:

Reg. Date: 11/03/2020 (Man. Year: 2019) Chassis No: KMHD841CMLU029827

86796 km Colour: Black Odometer:

Engine Capacity: 1591 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 205/55 R16 Rear Tyre Size: Front Left Side: Triangle 7 mm Rear Left Side: Triangle 7 mm Front Right Side: Triangle 7 mm Rear Right Side: Triangle 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		9,018.88	3,087.60	5,931.28	65.77
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,787.50	1,060.00	727.50	40.70
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	10,806.38	4,147.60	6,658.78	61.62
	Approved Total (Overridden) (S\$)		3,300.00		
	(S\$)	10,806.38	3,300.00	7,506.38	69.46
	+ GST 8.00/8.00% (S\$)	864.51	264.00	600.51	69.46
	Nett Amount (S\$)	11,670.89	3,564.00	8,106.89	69.46

INSPECTION

Date Inspected:

Date of Assignment: 28/07/2023

> Garage 13 Pte Ltd (HQ) 26/07/2022 Inspected At:

8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #03-46

Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: **BRYAN TANI** Manager: **CELINE FONG**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

8/1/23, 9:51 AM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Aug 2023)

Parts: HYUNDAI AD AVANTE 1.6 GLS S (A) (Catalogue:Merimen Singapore 1.0) 143

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMS7124B)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with Validity:

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,910.30 FL	*- FL
2	2		*BONNET HINGE	Not Necessary	110.40 FL	*- FL
3	1		*BONNET LOCK	Not Necessary	75.00 FL	*- FL
4	1		*BONNET INSULATOR	Not Necessary	122.00 FL	*- FL
5	1		*FRONT BUMPER	Deformed	674.00 FL	*494.00 FL
6	1		*FRONT BUMPER SPONGE	Not Necessary	132.00 FL	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	705.00 FL	*- FL
8	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	121.00 FL	*- FL
9	1		*FRONT BUMPER SIDE RETAINER LH	Cracked	31.20 FL	*31.20 FL
10	1		*FRONT BUMPER LAMP LH	Defaced/Cracked	211.20 FL	*211.20 FL
11	1		*FRONT BUMPER AIR GRILLE LH	Cut/Deformed	52.00 FL	*52.00 FL
12	1		*FRONT BUMPER SIDE TRIM LH	Not Necessary	32.00 FL	*- FL
13	1		*FRONT BUMPER AIR DUCT (AIR CURTAIN) LH	Not Necessary	75.50 FL	*- FL
14	1		*FRONT BUMPER LOWER LIP	Not Necessary	131.20 FL	*- FL
15	1		*FRONT BUMPER TOP RUBBER SEAL	Not Necessary	42.10 FL	*- FL
16	1		*FRONT BUMPER UPPER SUPPORT LH	Cracked	77.20 FL	*77.20 FL
17	1		*FRONT BUMPER LOWER BEAM	Not Necessary	199.40 FL	*- FL
18	1		*FRONT RADIATOR GRILLE ASSY WITH LOGO	Not Necessary	981.80 FL	*- FL
19	1		*HEADLAMP LH	Broken	1,756.00 FL	*1,756.00 FL
20	1		*HEADLAMP LOWER SUPPORT BRACKET LH	Cracked	68.90 FL	*68.90 FL
21	1		*FRONT FENDER LH	Buckled	966.50 FL	*966.50 FL
22	1		*FRONT FENDER INNER SHIELD LH	Not Necessary	99.00 FL	*- FL
23	1		*FRONT SUPPORT PANEL	Not Necessary	979.50 FL	*- FL
24	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	125.00 FL	*- FL
25	1		*RESONATOR ASSY	Torn/Deformed	165.00 FL	*165.00 FL
26	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
27	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	15.00 FS	*- FS
28	1		*SET FRONT RADIATOR GRILLE CLIPS	Not Necessary	15.00 FS	*- FS
29	1		*SET FRONT FENDER INNER SHIELD CLIP LH	Not Necessary	40.00 FS	*- FS
30	1		*SET BONNET INSULATOR CLIPS	Not Necessary	40.00 FS	*-FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 10,003.20 3,852.00 - List Item Discount on L Items 10.00/20.00% (S\$) 984.32 764.40

Total Parts (S\$)

9,018.88

3,087.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE PARTS REPAIR COLUMN INCLUSIVE OF REPLACEMENT PARTS	New	720.00	400.00
2	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE, PAINT / MATERIAL	New	750.00	600.00
3	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	50.00	30.00
4	PROGRAMMING / DIAGNOSTIC AND FAULTY CODE RESET	New	200.00	0.00
5	WIRING / BULB CHECKING (INCLUSIVE OF RE-FOCUS / RE-ADJUST ON ANGLE OF LIGHT INTENSITY)	New	67.50	30.00
	Gross Labour Cost (S\$)		1,787.50	1,060.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >