

TOH PAINTING & SERVICES PTE LTD
Block 3 Woodlands Road Unit 391C&G
Yew Tee Industrial Estate
Singapore (677966)

Phone 67631055
Fax 67636151
GST Number 20-0311427-D

TAX INVOICE

LOW BENG CHUAN
273B JURONG WEST AVENUE 3
#13-29
SINGAPORE 642273

Phone: 9021 8867

Fax:

Invoice Number: 103346

Date	Delivery	Customer	Order Number	Packing Slip	Internal Reference	Sales Person	Page
10-Jul-23	26-May-23	SLU7789J	T / NOAH		SLU7789J	0000	1

Code	Description	Quantity	Unit	Price	Discount	Amount
	LUMP SUM REPAIRS					
	TO SUPPLY SPARE PARTS, REPAIR / PANEL BEATING, WELDING, WIRING CHECKING, PUTTY AND SPRAY PAINTING & OTHER CHARGES	1		\$7,850.00		\$7,850.00
	CONTRACT REPAIR AS RECOMMENDED					

SGD: EIGHT THOUSAND FOUR HUNDRED SEVENTY-EIGHT ONLY



Authorized Signature for TOH PAINTING & SERVICES PTE
LTD

Total Net	\$7,850.00
GST	\$628.00
Invoice Total Including GST	\$8,478.00

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters
Blk 2 Rivervale Link, #09-02 Singapore 545040
Mobile: 9007 5234
Email: constant_as@yahoo.com.sg
RCB No. 53138015K

INVOICE

To: Low Beng Chuan
273B Jurong West Ave 3
#13-29
Singapore 642273

Date : 23/06/2023
Invoice No : IV23-06033/CAS

Particulars	Amount
Fee For Services Rendered In Respect Of: Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle SLU 7789J (Inclusive Of Photographs And Transport Charges) Our reference : CAS/23-06/033	\$582.00
Total	\$582.00

E. & O.E

Constant Appraiser Services



Cheque Should Be Crossed And Made Payment To 'Constant Appraiser Services'

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

Automobile Inspection Report

To: Low Beng Chuan 273B Jurong West Ave 3 #13-29 Singapore 642273	Date : 23/06/2023 Reference No : CAS/23-06/033																				
<u>General Information</u>																					
Registration No. : SLU 7789J Accident Date : 26/05/2023																					
<u>Particulars of Damaged Vehicle</u>																					
Colour : Pearl White Engine Capacity : 1797 cc Mileage (KM) : 357406 Chassis No. : ZWR800270699 Registration Date : 14/12/2017	Make & Model : Toyota Noah Hybrid Pre-Accident Condition : Good Engine No. : 2ZR8195605 Steering : In Order Brake : In Order																				
<u>Tyre Condition</u>																					
	<table><thead><tr><th></th><th>Size</th><th>Make</th><th>Balance</th></tr></thead><tbody><tr><td>R/H Front Tyre</td><td>225/35R19</td><td>SUREGRIP</td><td>80%</td></tr><tr><td>L/H Front Tyre</td><td>225/35R19</td><td>SUREGRIP</td><td>80%</td></tr><tr><td>R/H Rear Tyre</td><td>235/35R19</td><td>PIRELLI</td><td>80%</td></tr><tr><td>L/H Rear Tyre</td><td>235/35R19</td><td>PIRELLI</td><td>80%</td></tr></tbody></table>		Size	Make	Balance	R/H Front Tyre	225/35R19	SUREGRIP	80%	L/H Front Tyre	225/35R19	SUREGRIP	80%	R/H Rear Tyre	235/35R19	PIRELLI	80%	L/H Rear Tyre	235/35R19	PIRELLI	80%
	Size	Make	Balance																		
R/H Front Tyre	225/35R19	SUREGRIP	80%																		
L/H Front Tyre	225/35R19	SUREGRIP	80%																		
R/H Rear Tyre	235/35R19	PIRELLI	80%																		
L/H Rear Tyre	235/35R19	PIRELLI	80%																		
<u>Inspection</u>																					
Repairer : Toh Painting & Services Pte Ltd Blk 3C Woodlands Road, 391C/G Yew Tee Industrial Estate, Singapore 677966																					
<u>Adjustment And Recommendation Cost Of Repair</u>																					
Repairer's Estimate : \$12,382.99 Revised Amount : \$7,850.00 Less Excess : - Nett Total : \$7,850.00																					
<u>Remarks</u>																					
(A) Survey was done on 01/06/2023 (B) The survey was conducted entirely on WITHOUT PREJUDICE basis. (C) We have NOT given any instruction to authorize the repair of the vehicle.																					

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deem to be valid.

Constant Appraiser Services

Vehicle No : SLU 7789J

Our ref : CAS/23-06/033

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT – LIST ITEMS</u>					
1	1pc	Front door LH	Dented/Warped	1,506.15	1,506.15
2	1pc	Front door outer handle LH	Grazed/Jammed	320.53	320.53
3	1pc	Front door glass channel LH	Necessary	91.20	91.20
4	1pc	Front door weatherstrip LH	Necessary	119.22	119.22
5	1pc	Front door lower rubber seal LH	Necessary	25.67	25.67
6	1pc	Front door rubber stopper LH	Necessary	38.16	38.16
7	1pc	Front door lock LH	Serviceable	216.83	-
8	1pc	Sliding door LH	Dented/Warped	2,504.51	2,504.51
9	1pc	Sliding door glass channel LH	Necessary	96.50	96.50
10	1pc	Sliding door outer handle LH	Repair	113.70	-
11	1pc	Wing mirror assy LH	Grazed/Jammed	510.96	510.96
12	1pc	Front shock absorber RH	Bent	713.10	713.10
13	1pc	Front lower arm RH	Bent	656.39	656.39
14	1pc	Front knuckle arm RH	Bent	517.69	517.69
15	1pc	Front knuckle arm bearing RH	Necessary	91.35	91.35
16	1pc	Front wheel hub RH	Bent	545.54	545.54
17	1pc	Front stabilizer bar	Serviceable	511.69	-
18	1pc	Front stabilizer bar link RH	Bent	92.96	92.96
19	1pc	Front drive shaft RH	Serviceable	494.50	-
20	1pc	Steering tie rod end RH	Serviceable	610.66	-
				9,777.31	7,829.93
Less 25%				(2,444.32)	(1,957.48)
Sub total				7,332.99	5,872.45
<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>					
1	1pc	Front sport rim RH	Grazed/Warped	920.00	920.00
2	1pc	Front tyre RH	Serviceable	550.00	-
3	1set	Front door board clip LH	Necessary	65.00	65.00
4	1set	Sliding door board clip LH	Necessary	55.00	55.00
Part total				8,922.99	6,912.45

Constant Appraiser Services

Vehicle No : SLU 7789J

Our ref : CAS/23-06/033

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>LABOUR & MISC. CHARGES</u>			
1		Repair & replace damaged parts		1,000.00	800.00
2		Spray paint affected area (Pearl White)		1,600.00	1,400.00
3		Remove & refix front undercarriage		300.00	250.00
4		Check wheel alignment		120.00	100.00
5		Diagnose & reset system after repair		360.00	250.00
6		Spray anti rust on affected area		80.00	60.00
			Grand total	12,382.99	9,772.45
Recommended cost of lump sum repair (To its pre-accident condition)					7,850.00

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$7,850.00** on a contractual basis. Under normal circumstances, the repair period would be about **5 (Five)** working days.

Yours faithfully,




Constant Appraiser Services







The stamp is circular with the text "CONSTANT APPRAISER SERVICES" around the perimeter and "CAS" in the center. There is a small star at the bottom of the circle.

Lim Yong Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA


Constant Appraiser Services




Constant Appraiser Services



Constant Appraiser Services



Constant Appraiser Services



Constant Appraiser Services

