

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG23000184/TVP3M4**Date:** 06/04/2023REFERENCE

Insured/Claimant: LIM WEI SIONG Policy No: 7210108791
Date of Loss: 30/12/2022 Nature of Claim: OD Claim No: 4817008765SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNC3989X**
Make & Model: AUDI A3, 1.5 SEDAN TFSI S TRONIC (A) Engine No: DFY292694
Reg. Date: 10/09/2021 (Man. Year: 2021) Chassis No: WAUZZZGY4NA006752
Colour: Purple Odometer: 23989 km
Engine Capacity: 1498 cc
Market Value/New Car Price: S\$148,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35R19 Rear Tyre Size: 235/35R19
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,241.00	2,115.60	1,125.40	34.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,722.00	1,722.00	1,000.00	36.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,963.00	3,837.60	2,125.40	35.64
- Excess (\$\$)	400.00	400.00	0.00	0.00
(\$\$)	5,563.00	3,437.60	2,125.40	38.21
+ GST 8.00/8.00% (\$\$)	445.04	275.01	170.03	38.21
Nett Amount (\$\$)	6,008.04	3,712.61	2,295.43	38.21

INSPECTION

Date of Assignment: 06/01/2023
Date Inspected: 05/01/2023 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - RH	Bent	2,466.00 FS	*1,972.80 FS
2	1		*REAR DOOR OUTER SEAL - RH	Necessary	179.00 FS	*142.80 FS
3	1		*REAR DOOR CATCH	Not Necessary	93.00 FS	*- FS
4	1		*REAR QUARTER WINDOW GUIDE RAIL - RH	Not Necessary	52.00 FS	*- FS
5	1		*REAR WINDOW REGULATOR - RH	Not Necessary	251.00 FS	*- FS
6	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
F=Franchise part, S=SpcNett.						
Total Parts (S\$)					3,241.00	2,115.60

LKK Auto Consultants Pte Ltd/SNC3989X/06/04/2023 07:41

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES	New	360.00	360.00
2	TO DISMANTLE AND RENEW RHS REAR DOOR, ALIGN TO POSITION. REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY RHS REAR DOOR	New	1,000.00	550.00
4	TO CARRY OUT STICKER WRAP ON RHS REAR DOOR	New	120.00	120.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$)			2,722.00	1,722.00

LKK Auto Consultants Pte Ltd/SNC3989X/06/04/2023 07:41

< END OF ESTIMATES >