

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	HSBC LIFE (SING		Ref:	CS3/HSB23007821/Tnp3e2	
	10 MARINA BOULE	EVARD AY FINANCIAL CENTRE TOWER	Date		
	ATTN: TEO KITTY		Code	: HSB	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 8741G	Veh. Inspected	FBR 5934D	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S3M04OHX	Excess (\$)	0.00	
	Assign From	TEO KITTY	Assign Date	02/08/2023	
2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA NMAX	c.c	155	
	Engine No.	HIDDEN	Year of Reg.	2022	
	Chassis No.	MH3SG5680MK116272	Colour	GREY	
	Odometer	-	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	110/70 R13	MAXXIS	5 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	130/70 R13	MAXXIS	5 mm	
	L/H Rear Tyre			mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5.	General Information				
	Accident Date	27/07/2023	Inspect Date / Time	02/08/2023 (01:50 PM)	
	Survey held at	BIKE DYNAMIC CENTRE			
	BLK 6 DEFU LANE 10 #01-55 SINGAPORE 539187				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500-\$4,500				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:	5 Wo	king Days	
	Report Ref No. CS3/HSB23007821/Tnp3e2				

Report Ref No. CS3/HSB23007821/Tnp3e2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A
Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser