Blk 495-E Tampines Street 43, #04-368 Singapore 524495. Tel: 97859520 Reg.No.: 53436440C Insurance Loss Adjuster Licensed Appraiser (Member Of Singapore Automobile Appraisers Association)

_		AU	<u>LOMOBILE IN</u>	SPECTION REPORT	· <del>-</del>	
m/s	Futar Ente	erprises Pte Ltd		Date:	10/3/2023	
	19 Chang	i N Way,		Our Ref:	TP/2022/026	511
	Singapore	498786.		Claim No:	-	
				Policy No:	-	
PARTIC	ULARS C	OF VEHICLE		AA		
Reg No :	GBD8213	3E	Make/Model:	Nissan Cabstar Lorry	Year:	29/5/2015
Engine No:	ZD30343	990K	Chassis No:	JN1SC2F24Z0856764	Colour:	M. Gold
Mileage :	305271 K	Cm .	Engine Cap:	2953 сс	Seat Belt:	Yes
Aircon:	Yes		Radio/Cassette	Yes	Rims:	Standard
VEHICL:	E COND	ITION ( Static Te	st Only )		·	
Brakes:	Serviceab	le	Handbrakes:	Serviceable	Steering:	Serviceable
General Bod	ly Works:	Good				
TYRE CO	ONDITIO	<u>DNS</u>				
Front O/S:	6		Rear O/S:	6\6	Make: Yokohama	
Front N/S:	6		Rear N/S:	6\6	Size: 195\70R15	\ 155R12
	(Remaining	Estimated Life Of Tyre in r	nm)			
GENERA	L DESC	RIPTION OF DA	MAGES	and the state of t		
				alting in the front cabin bent/to	wisted; n/s front door	bent
The vehicle	sustained an	impact on its front n/s	and rear portion resu	ulting in the front cabin bent/to		
The vehicle and buckled	sustained an ; front panel	impact on its front n/s, n/s pillar, n/s wheel ar	and rear portion resu	-	reinforcement, front	cabin lock,
The vehicle and buckled cabin spring	sustained an ; front panel, , cabin mour	impact on its front n/s, n/s pillar, n/s wheel ar	and rear portion resu ch, n/s door back pa /s headlamp, grille, v	nel, front bumper bracket and	reinforcement, front ed/broken; rear chassi	cabin lock, s, tailgate,
The vehicle and buckled cabin spring tailgate lower	sustained an ; front panel, , cabin mour	impact on its front n/s, n/s pillar, n/s wheel ar	and rear portion resu ch, n/s door back pa /s headlamp, grille, v	nel, front bumper bracket and riew mirror, dashboard cracke	reinforcement, front ed/broken; rear chassi	cabin lock, s, tailgate,
The vehicle sand buckled; cabin spring tailgate lower damages)	sustained an ; front panel, , cabin mour er members,	impact on its front n/s, n/s pillar, n/s wheel ar	and rear portion resu ch, n/s door back pa /s headlamp, grille, v	nel, front bumper bracket and view mirror, dashboard cracket np, reverse sensor cracked. (s	reinforcement, front ed/broken; rear chassi	cabin lock, s, tailgate,
The vehicle sand buckled; cabin spring tailgate lower damages)	sustained an ; front panel, , cabin mour er members, ident :	impact on its front n/s, n/s pillar, n/s wheel ar nting bent; w/screen, n/side gate, metal canopy	and rear portion rest ch, n/s door back pa /s headlamp, grille, v / bent/dented; taillan	nel, front bumper bracket and riew mirror, dashboard cracket np, reverse sensor cracked. (s Date of Insp	reinforcement, front ed/broken; rear chassi ee attached schedule	cabin lock, s, tailgate,
The vehicle sand buckled; cabin spring tailgate lower damages)  Date of Accident	sustained an ; front panel, , cabin mour er members, ident :	impact on its front n/s, n/s pillar, n/s wheel ar ating bent; w/screen, n/s side gate, metal canopy 28/10/2022	and rear portion resuch, n/s door back pa /s headlamp, grille, w / bent/dented; taillan	nel, front bumper bracket and riew mirror, dashboard cracket np, reverse sensor cracked. (s Date of Insp	reinforcement, front ed/broken; rear chassi ee attached schedule section : 3/11/22	cabin lock, s, tailgate,
The vehicle sand buckled; cabin spring tailgate lower damages)  Date of Accident	sustained an ; front panel, , cabin mour er members, ident :	impact on its front n/s, n/s pillar, n/s wheel ar nting bent; w/screen, n/s side gate, metal canopy 28/10/2022  Precise Auto Service	and rear portion resuch, n/s door back pa /s headlamp, grille, w / bent/dented; taillan	nel, front bumper bracket and riew mirror, dashboard cracket np, reverse sensor cracked. (s Date of Insp	reinforcement, front ed/broken; rear chassi ee attached schedule section: 3/11/22 ted By: Miss Arine	cabin lock, s, tailgate,
The vehicle sand buckled; cabin spring tailgate lower damages) Date of Acci	sustained an ; front panel, , cabin mour er members, ident :	impact on its front n/s, n/s pillar, n/s wheel ar nting bent; w/screen, n/s side gate, metal canopy 28/10/2022  Precise Auto Service 1 Kaki Bukit Ave 6,	and rear portion resuch, n/s door back pa /s headlamp, grille, w / bent/dented; taillan #02-33/34	nel, front bumper bracket and riew mirror, dashboard cracket np, reverse sensor cracked. (s Date of Insp As Reques	reinforcement, front ed/broken; rear chassi ee attached schedule section: 3/11/22 ted By: Miss Arine	cabin lock, s, tailgate,
The vehicle sand buckled; cabin spring tailgate lower damages) Date of Accion Survey Held	sustained an ; front panel, , cabin mounter members, ident: I At:	impact on its front n/s, n/s pillar, n/s wheel ar nting bent; w/screen, n/s side gate, metal canopy  28/10/2022  Precise Auto Service 1 Kaki Bukit Ave 6, Singapore 417883.	and rear portion resuch, n/s door back pa /s headlamp, grille, w / bent/dented; taillan #02-33/34	nel, front bumper bracket and riew mirror, dashboard cracket np, reverse sensor cracked. (s Date of Insp As Reques	reinforcement, front ed/broken; rear chassi ee attached schedule section: 3/11/22 ted By: Miss Arine	cabin lock, s, tailgate,
The vehicle sand buckled; cabin spring tailgate lower damages) Date of Accion Survey Held  ADJUST Repairer's E	sustained an ; front panel , cabin mounter members, ident: I At :  MENT A stimate:	impact on its front n/s , n/s pillar, n/s wheel ar nting bent; w/screen, n/s side gate, metal canopy  28/10/2022  Precise Auto Service 1 Kaki Bukit Ave 6, Singapore 417883.  ND RECOMMEN	and rear portion resuch, n/s door back pa /s headlamp, grille, w / bent/dented; taillan #02-33/34	nel, front bumper bracket and riew mirror, dashboard cracket np, reverse sensor cracked. (s Date of Insp As Reques	reinforcement, front ed/broken; rear chassi ee attached schedule section: 3/11/22 ted By: Miss Arine	cabin lock, s, tailgate,
The vehicle sand buckled; cabin spring tailgate lower damages) Date of Acci	sustained an ; front panel, , cabin mourer members, ident:  I At:  MENT A stimate:	impact on its front n/s , n/s pillar, n/s wheel ar nting bent; w/screen, n/s side gate, metal canopy  28/10/2022  Precise Auto Service 1 Kaki Bukit Ave 6, Singapore 417883.  ND RECOMMEN \$41,978.43	and rear portion resuch, n/s door back pa /s headlamp, grille, w / bent/dented; taillan #02-33/34	nel, front bumper bracket and riew mirror, dashboard cracket np, reverse sensor cracked. (s Date of Insp As Reques	reinforcement, front ed/broken; rear chassi ee attached schedule section: 3/11/22 ted By: Miss Arine	cabin lock, s, tailgate,
The vehicle : and buckled; cabin spring tailgate lowe damages) Date of Acci Survey Held  ADJUST Repairer's E Revised Am	sustained an ; front panel, , cabin mourer members, ident:  I At:  MENT A stimate:	impact on its front n/s , n/s pillar, n/s wheel ar nting bent; w/screen, n/s side gate, metal canopy  28/10/2022  Precise Auto Service 1 Kaki Bukit Ave 6, Singapore 417883.  ND RECOMMEN \$41,978.43 \$34,810.36	and rear portion resuch, n/s door back pa /s headlamp, grille, w / bent/dented; taillan #02-33/34	nel, front bumper bracket and riew mirror, dashboard cracket np, reverse sensor cracked. (s Date of Insp As Reques	reinforcement, front ed/broken; rear chassi ee attached schedule section: 3/11/22 ted By: Miss Arine	cabin lock, s, tailgate,

Remarks: The Survey was conducted strictly without prejudice.

photos were taken at the time of inspection and attched.

75

#### ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

Veh.No:	GBD8213E			
QTY	DESCRIPTION OF PARTS AND LABOUR	CONDITION	REPAIRER EST	OUR REVISED
			(\$)	(\$)
	TO SUPPLY (List item)			
1 pc	tailgate	bent/dented	1,688.40	1,688.40
l pc	tailgate lower member	bent/dented	343.80	343.80
l pc	tailgate "Nissan" sticker 🗸	necessary	32.10	32.10
l pc	front bumper 🗸	bent/torn	667.10	667.10
l pc	front bumper reinforcement X NN	bent	590.60	590.60
2 pcs	front bumper bracket 🗸	n/s bent	194.20	97.10
l pc	n/s front door 🗸	bent/buckled	1,396.50	1,396.50
1 pc	front n/s pillar X Repair	bent	1,646.40	1,646.40
l pc	rear spare tyre bracket X NN	bent	289.70	289.70
•			6,848.80	<b>4225</b> 6,751.70
	Less 30%		2,054.64	2,025.51
			4,794.16	2957.5 4,726.19
	TO SUPPLY (NETT ITEM)		,	
1 pc	front n/s pillar inner	bent (repair)	388.80	-
3 pcs	tailgate hinge 🗸	2 pcs bent	484.20	169.4 322.80
2 pcs	tailgate side lock 🗸	bent	366.40	130.8 366.40
2 pcs	tailgate side lock bracket X NN	bent	182.40	182.40
2 pcs	tailgate rubber stopper	n/s missing	38.80	19.40
2 pcs	tailgate rubber stopper bracket	bent (repair)	176.20	-
2 pcs	taillamp 🗸	сгаскеd	225.00	225.00
2 pcs	taillamp bracket 🗸	bent	363.40	242.8 363.40
1 pc	rear step member \( \square \)	bent	480.00	385.1 480.00
l pc	rear number plate lamp 🗸	broken	69.80	69.80
1 pc	rear number plate lamp holder 🗸	bent	88.10	88.10
l pc	spare tyre carrier \( \square \)	bent	475.90	231.6 475.90
l pc	front panel	n/s bent/dented	1,412.70	1,412.70
l pc	front panel "Cabstar" emblem	dented	38.10	38.10
2 pcs	headlamp /	n/s broken	946.80	384.5 473.40
2 pcs	headlamp lower garnish \square	n/s cracked	150.20	75.10
2 pcs	front side panel	n/s bent	779.80	389.90
l pc	front grille \	cracked	578.60	469.4 578.60
l pc	front grille emblem	serviceable	55.10	_
8 pcs	front grille clip 🗸	necessary	51.20	51.20
l pc	front grille inner garnish	cracked	34.40	34.40
1 pc	front wiper panel	cracked	494.60	494.60
8 pcs	front wiper panel clip	necessary	51.20	51.20
l pc	front wiper linkage	serviceable	151.50	
l pc	front n/s view mirror (rount)	cracked	55.30	55.30
l pc	front n/s view mirror garnish	not such part	22,90	
l pc	front n/s view mirror bracket $\checkmark$	bent	191.90	191.90
l pc	front n/s view mirror garnish	cracked	111.30	111.30
ı po	total c/f	<b>{</b>	8,464.60	6,550.90

#### ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

Veh.No	3	GBD8213E
A CITITIO		ODDODIOL

QTY	DESCRIPTION OF PARTS AND LABOUR	CONDITION	REPAIRER EST	OUR REVISED
	A service of the serv		(\$)	(\$)
	sub toa	1 b/f	8,464.60	6,550.90
рс	front n/s view mirror	cracked	171.80	171.80
рс	front windscreen glass	cracked	991.00	991.00
рс	front windscreen glass top moulding \square	necessary	93.50	93.50
рс	front windscreen glass lower moulding	necessary	34,70	34.70
4 pcs	front windscreen glass clip	necessary	77.00	77.00
рс	front windscreen glass inner seal	necessary	50.00	50.00
pcs	front n/s door hinge	bent	112.20	112.20
pcs	front n/s door weatherstrip	torn	302.20	192.7 302.20
pcs	front door lock	n/s bent	333.40	166.70
рс	front n/s door trim board \square	cracked	755.90	755.90
pcs	front n/s door trim board clip	necessary	51.20	51.20
рс	front n/s door glass regulator	bent	288.10	288.10
рс	front n/s door glass /	broken	760.00	442.9 760.00
pcs	front door glass channel rubber X NN	n/s cut	370.40	× 185.2
2 pcs	front door glass channel bracket X NN	n/s bent	382.20	× 191.1
2 pcs	front door rubber stopper	n/s torn	38.80	19.4
pc	front n/s door glass outer moulding	bent	181.40	181,4
pc	front n/s door glass vertical moulding	bent	141.80	141.8
рс	front n/s step board	cracked	139.40	139.4
рс	front n/s pillar trim	cracked	114.70	114.7
рс	front n/s wheel arcch	bent	399.80	399.8
pc	front n/s wheel arch trim	bent	197.40	145.4 197.4
l pc	wiper washer tank	serviceable	85.40	110.1127.1
pc	wiper washer motor	serviceable	95.10	
l pc	dashboard	cracked	1,689.90	1,689.9
pc pc	dashboard support member X NN	bent	869.60	869.6
pc	dashboard support member n/s bracket X NN	bent	91.40	91.4
pc	dashboard centre radio panel X NN	cracked	598.10	598.1
l pc	n/s console box X NN	cracked	399.80	399.8
	cabin front mounting X NN	n/s bent	530.20	265.1
2 pcs	cabin rear mounting X NN	n/s bent	596.80	298.4
l pc	cabin spring unit X NN	bent	1,682.90	1,682.9
l pc		bent	362.20	362.2
2 pcs	cabin lock X NN		79.20	79.2
2 pcs	cabin stopper X NN	damaged	451.20	451.2
2 pcs	cabin spring bracket X NN	bent		1,310.6
l pc	aircon evaporator	cracked cracked	1,310.60 881.00	881.0
l pc		serviceable	369.10	881.0
l pc	aircon discharge pipe	The man with the state of the s	299.80	3
pc	aircon sustion pipe	serviceable		200.1
pc	spare tyre rim (big) X NN	bent	388.10	388.1
l pc	spare tyre rim (small) X NN	bent 13772.7	278.40	278.4
	100/	13/12./	25,510.30	21,621.3
	Less 10%	12395.43	2,551.03	2,162.1
		000.10	22,959.27	19,459.1

### ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

Veh.No: GBD8213E

GBD8213E				t
DESCRIPTION OF PARTS AND LABOUR	CONDITION	REPAIRER EST	OUR REVISED	
		(\$)	(\$)	
TO SUPPLY (SPECIAL NETT ITEM)				İ
rear canopy assy	bent	2,800.00		
tailgate aluminium plate 🗸	bent	400.00	400.00	35
	missing	35.00	35.00	15
	· ·	20.00	20.00	10
A CONTRACTOR OF THE CONTRACTOR	1	20.00	20.00	10
	•	1	L	
	1 -	1	5	Š
	1 *		1	_/
The state of the s	1	t t	I .	1
1	1			
	1		ì	1
TOVELSO SCIENCE	damaged		<del> </del>	20
		1,103.00	3,233.00	
Total Spare Parts		31,918.43	27,420.36	
LABOUR CHARGE				
Towing. (2 trip)		240.00	240.00	50
To do tailgate art work NN		300.00	-	
To check and reconnect damaged wiring, check lighting and focus headlamp alignment after repairs.		280.00	150.00	30
To tuff-kote on cut and welded panel and other accident affected areas.		350.00	300.00	80
To remove and lift front cabin to enable repairs.		800.00	600.00	18
To remove and renew dashboard assy.		350.00	250.00	20
To remove and renew aircon blower and evaporator and refill aircon gas after repairs.		350.00	250.00	15
To remove and refix clutch, brake pedal, master pump, booster to enable repairs and bleed system after repairs.		300.00	X NN 200.00	
To remove and renew spare tyre carrier and bracket.		150.00	X NN 80.00	
To remove and transfer n/s front door parts to new door.		220.00	0.00	
10 tomove and maister his front door parts to new door.	1	1		
	TO SUPPLY (SPECIAL NETT ITEM) rear canopy assy tailgate aluminium plate  rear mumber plate  rear "70km/h" sticker  rear "12pax" sticker  front w/screen glass sealant  ERP bracket  n/s front door R.O.C sticker  spare tyre (big) spare tyre (small) reverse sensor   Total Spare Parts  LABOUR CHARGE Towing. (2 trip)  To do tailgate art work NN  To check and reconnect damaged wiring, check lighting and focus headlamp alignment after repairs.  To tuff-kote on cut and welded panel and other accident affected areas.  To remove and lift front cabin to enable repairs.  To remove and renew dashboard assy.  To remove and renew aircon blower and evaporator and refill aircon gas after repairs.  To remove and refix clutch, brake pedal, master pump, booster to enable repairs and bleed system after repairs.  To remove and renew spare tyre carrier and bracket.	TO SUPPLY (SPECIAL NETT ITEM) rear canopy assy tailgate aluminium plate / rear number plate / rear "rokm/h" sticker / rear "12pax" sticker / recessary recessary necessary necessary necessary necessary necessary necessary recessary recessary necessary necessary spare tyre (big) reverse sensor / rever	TO SUPPLY (SPECIAL NETT ITEM) rear canopy assy tailgate aluminium plate rear number plate rear "T0km/h" sticker rear "12pax" sticker recessary rec	TO SUPPLY (SPECIAL NEIT ITEM) rear canopy assy taligate aluminium plate  rear rumber plate  rear "ToRM's ticker  reasons  reas

#### ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

Veh.No: GBD8213E

Veh.No:	GBD8213E	<del></del>	· · · · · · · · · · · · · · · · · · ·	
QTY	DESCRIPTION OF PARTS AND LABOUR	CONDITION	REPAIRER EST (\$)	OUR REVISED (\$)
	To apply primer, to putty and paint front panel, n/s front door, n/s front pillar, n/s front wheel arch panel, cabin floor panel, grille, wiper panel, n/s door back panel, tail gate, tailgate lower member, side gate and other affected areas.		2,800.00	2000 2,200.00
	To remove damaged parts, jack out, straighten and knock n/s front pillar inner, cabin floor panel, n/s front door back panel, rear chassis frame, side gate. Cut and weld front panel, front n/s pillar, front n/s wheel arch,			
	tailgate lower member and renew recommended parts.		3,800.00	2800 3,000.00
	Total Labour Charges		10,060.00	5490 7,390.00
	GRAND TOTAL		41,978.43	34,810.36
Note:	The repairer had agreed to undertake the repair on Lump Sum basis of \$27,850.00 nett to reinstate this vehicle to its pre-accident condition.  (repairer discretion to repair parts, to replace with second hand parts, or to replace with OEM or Genuine parts)	End of Report	21527.93 -20%: 17200 16 Days	
		1		

TNECNIV SERVICES

\_\_\_\_\_\_

Vincent Ng Seow Gim