

Ding Auto Pte Ltd (Co.Reg.No:201311788Z)

176 Sin Ming Drive #04-06, Sin Ming Autocare
Singapore 575721

Tel: 64521208 Fax: 64520614 Email: ding@dingauto.sg;kenneth.ding@dingauto.sg

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2006541754	Date of Loss:	27/07/2023
Vehicle Reg. No.:	SNL2771R	Driveable?	
Driver Age/Info:	26 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	GETGO SG SPV B PTE LTD		
Driver:	NURUL HUDA BINTIE HASSAN		

Make/Model:	SUZUKI SWIFT, 1.2 GLX CVT (A)	Vehicle Reg. Date:	23/06/2023
Vehicle Colour:	Red		
Engine No:	K12D1236528	Chassis No:	JSAAZCA3S00584756
Odometer:	0 KM		

Paint Type:
Total Loss? NO
Est. Duration of Repair (day) 14 5 days

*Not attached
Recovery by party
Ex @ 20000*

Description of Accident/Loss COLLIDED INTO SIDE KERB
Present Location: DING AUTO PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	5,938.00
Miscellaneous Items	430.00
Labour	1,380.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	7,748.00
+ GST 8.00% (\$\$)	619.84
Nett Amount (\$\$)	8,367.84

This claim is handled by: LYNN YAP WEI LIN

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Aug 2023)
 Parts: 144 SUZUKI SWIFT 1.2 GLX CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Ding Auto Pte Ltd/SNL2771R/03/08/2023 11:47
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BUMPER	CM	0.00	0.00	*950.00 F ✓
2	1		*FRONT BUMPER BRACKET LHS	DTI	0.00	0.00	*15.00 F ✓
3	1		*FRONT FENDER INNERSHIELD LHS	T ₁	0.00	0.00	*120.00 F ✓
4	1		*FRONT RIM LHS	RD	0.00	0.00	*800.00 F ✓
5	1		*FRONT ABSORBER LHS		0.00	0.00	*380.00 F ?
6	1		*FRONT ABSORBER MOUNTING LHS		0.00	0.00	*28.00 F ?
7	1		*FRONT LOWER ARM LHS	R ₁	0.00	0.00	*270.00 F ✓
8	1		*FRONT ABS SENSOR LHS		0.00	0.00	*220.00 F ?
9	1		*FRONT LINKAGE LHS	D ₁	0.00	0.00	*100.00 F ✓
10	1		*FRONT FENDER LHS	R ₁	0.00	0.00	*320.00 F ✓
11	1		*FRONT KNUCKLE LHS	R ₁	0.00	0.00	*340.00 F ✓
12	1		*FRONT DISC ROTOR LHS		0.00	0.00	*130.00 F ?
13	1		*FRONT BRAKE PAD LHS	L ₁	0.00	0.00	*170.00 F X
14	1		*FRONT CALIPER LHS	L ₁	0.00	0.00	*510.00 F X
15	1		*FRONT WHEEL BEARING HUB WITH BEARING LHS	B ₁	0.00	0.00	*420.00 F ✓
16	1		*DRIVE SHAFT LHS	R ₁	0.00	0.00	*900.00 F ✓
17	1		*TIE ROD END LHS		0.00	0.00	*95.00 F ?
18	1		*TIE ROD ARM LHS		0.00	0.00	*80.00 F ?
19	1		*TIE ROD BALL JOINT LHS		0.00	0.00	*90.00 F ?
						Total Parts (\$\$)	5,938.00

F=Franchise part.

Ding Auto Pte Ltd/SNL2771R/03/08/2023 11:47. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT BUMPER & FRONT FENDER INNERSHIELD LHS CLIPS	100.00
2	1	FRONT TYRE LHS	250.00
3	1	WHEEL ALIGNMENT	80.00
Sub Total (S\$)			430.00

Pr *Ma* *90252* *601*

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	LABOUR TO REMOVE & INSTALL - UNDERCARRIAGE ITEMS	New	500.00
2	REPAIR, PANEL BEAT & STRAIGHTEN - ACCIDENT AREAS	New	500.00
3	SPRAY PAINT - FRONT BUMPER	New	300.00
4	RUST PROOFING	New	80.00
Gross Labour Cost (S\$)			1,380.00

200 *400* *NZ* *X*

Ding Auto Pte Ltd/SNL2771R/03/08/2023 11:47. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Co
Va