LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO PC 7454Y

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate ($)	Our Adjusted ($)
1	REAR CENTRE BUMPER	DEFORMED/CRACKED	$2,568.00	$2,188.00
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	$770.00	$0.00
2	REAR BUMPER INNER BRACKET	SERVICEABLE	$345.00	$0.00
1	REAR RH BUMPER SIDE	DEFORMED/CRACKED	$950.00	$750.00
1	REAR BOOT COMPARTMENT	TO REPAIR SEE LABOUR	$3,200.00	$0.00
1	REAR RH CENTRE RED	GRAZED	$320.00	$320.00
1	REAR RH BOTTOM CLEAR	GRAZED/CRACKED	$210.00	$210.00
1	REAR RH BOTTOM RED	GRAZED/CRACKED	$320.00	$320.00
1	REAR BOOT COMPARTMENT LOCK	NOT NECESSARY	$650.00	$0.00
	LESS 10.00% DISCOUNT		($933.30)	($378.80)
			$8,399.70	$3,409.20

Labour				
	Description of Parts	Condition	Workshop Estimate ($)	Our Adjusted ($)
	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN. INCLUSIVE OF THE REPAIR OF REAR BOOT COMPARTMENT		$1,500.00	$500.00
	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY ON REAR DAMAGED PORTION		$1,800.00	$800.00
	TO CHECK THE WIRING SYSTEM TO FACILITATE THE REPAIR		$100.00	$30.00
			$3,400.00	$1,330.00

GRAND TOTAL	**$11,799.70**	**$4,739.20**

RECOMMENDED COST OF LUMP SUM REPAIRS **(TO ITS PRE-ACCIDENT CONDITION)**	**$3,750.00**
Report Ref No: CS1/SPF24080200/Eqp3e2	

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF $3,750-$4,200

CTY

STEVE CHEN TSUE YEE