CHIN CHUAN GARAGE

Blk 3006 Ubi Rd 1, #01-336 Singapore 408700
H/P: 96736356 (Jack) Fax: 6747 8378
Reg. No.: 50600700J

TP 1st Cap
Hui Rong

Name: Dou Yee Enterprises (S) Pte Ltd
Address: c/o Blk 3006 Ubi Rd 1
#01-336 Singapore 408700
Date: 6-Sep-24
Vehicle No.: YP 4401 U
Model: Hino XZU710R-HKFMS3

Items:

S/N	Description	Amount
1 pc	Front bumper Distorted	$ 1,240.00
1 pc	Front bumper inner bracket RHS Dmgd	$ 295.00
1 pc	Front bumper fog lamp RHS Cracked	$ 350.00
1 pc	Front bumper fog lamp inner garnish RHS New	$ 135.00
1 pc	Front grille New	$ 450.00
1 pc	Headlamp RHS Cut	$ 1,350.00
1 pc	Headlamp lower garnish RHS New	$ 95.00
1 pc	Front corner panel RHS Cracked	$ 205.00
1 pc	Front side mirror with bracket assy RHS New	$ 225.00
1 pc	Front door RHS Dented	$ 1,850.00
1 set	Front door company sticker New	$ 250.00
1 pc	Front door outer handle RHS New	$ 185.00
1 pc	Front door signal lamp RHS Missing	$ 165.00
1 pc	Front door inner garnish RHS	$ 225.00
2 pcs	Front door upper and lower hinge RHS New	$ 180.00
1 pc	Front step garnish RHS Cut	$ 265.00
1 pc	Front step garnish reflector RHS Cut	$ 95.00
1 pc	Front tyre mud flap RHS Cut	$ 220.00
1 pc	Rear tailgate aluminium corner assy RHS Distorted	$ 1,650.00
1 pc	Rear tailgate sliding door lock RHS Dmgd	$ 165.00
1 pc	Rear tailgate side panel RHS Repair	$ 480.00
1 pc	Rear tailgate side lock bracket RHS Dmgd	$ 145.00
1 pc	Front door 616 sticker (Emblem) } Missing	$ 115.00
1 pc	Front door Euro 5 (Emblem)	$ 125.00
1 set	Rear tailgate sliding door sticker New	$ 300.00
1 pc	Rear pillar } Repair	repair
1 pc	Front pillar	repair
		$ 9,420.00
		Less 10% $ 942.00
		Total $ 8,478.00

1 pc Front side mirror top bracket New @ 65 } Sent
1 pc Rear tailgate side step bracket RHS @ 205 }
1 pc Front fog lamp housing bracket RHS @ 125 }
Cracked

874
790
1490
150(SW)
300(SW)
45
50
5809
Less 10% 5228.10
S/N: 1050

CHIN CHUAN GARAGE

Blk 3006 Ubi Rd 1, #01-336 Singapore 408700
H/P: 96736356 (Jack) Fax: 6747 8378
Reg. No.: 50600700J

Labour

1)	To check wiring, lighting and re-setting	$	50.00
2)	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damage consistent to the accident. (including all repair parts)	$	1,200.00
3)	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	$	1,200.00
		$	**2,450.00**

1530

Adding
L/s 10/09/24

07 Days

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 7808.10

L/s : 6.2K