LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMF 9036C

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate ($)	Our Adjusted ($)
1	FRT FENDER LH	DENTED	$1,832.50	$912.20
1	FRT DOOR LH	TO REPAIR SEE LABOUR	$1,228.80	$0.00
1	SIDE MIRROR ASSY LH	TO REPAIR SEE LABOUR	$898.20	$0.00
	LESS 10.00% DISCOUNT		($395.95)	($91.22)
			$3,563.55	$820.98

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate ($)	Our Adjusted ($)
1	SUNDRIES (SAND PAPER, WELDING WIRE ETC.) (SN)	NOT NECESSARY	$50.00	$0.00
			$50.00	$0.00

Labour				
	Description of Parts	Condition	Workshop Estimate ($)	Our Adjusted ($)
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF FRT DOOR LH AND SIDE MIRROR ASSY LH		$600.00	$400.00
	TO REMOVE & REFIT WIRING SYSTEM AT BUMPER AND CHECK FOR PROPER FUNCTIONS	NOT NECESSARY	$100.00	$0.00
	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED		$600.00	$450.00
	TO VACUUM, WAXING & CLEAN	NOT NECESSARY	$50.00	$0.00
			$1,350.00	$850.00

GRAND TOTAL			**$4,963.55**	**$1,670.98**
RECOMMENDED COST OF LUMP SUM REPAIRS **(TO ITS PRE-ACCIDENT CONDITION)**				**$1,300.00**
Report Ref No: CS/LIP24090379/Tqh3e2				

MARKET VALUE: $56,000.00 (EST)-LTA REIMBURSEMENT VALUE: $19,283.00=NETT VALUE: $36,717.00

MTH

MOHAMAD TAUFIKH