ASSIGNMENT

From:	Date:
Estin. Cost:	

OD / TPPD / TP RES / OD RES / EVA / INV / MV

To In. Veh. Vehicle No:

ai W.O Regn m/s

of

Insured:

Policy No

Claims No

Sum Ens.   Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

	N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: **7** days   Res.: Yes or No

Lum Sum: %   3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SMV9577Z**   Yr Regn: **2020, Oct.**

Type: (M.Car) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: **Toyota Voxy Hybrid** cc **1797**

Colour: **Black**   A/C: Insured / Std / NI / NA

Sp.Reading: **104158**   T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: **ZWR800404189**

Gen. Cond: (Good) / Fair / Poor / Burnt

Steering: (Inorder) / Jammed / Leaked / Burnt or

Brake: (Inorder) / Jammed / Leaked / Burnt or

Modi: Nil / (S/Rim) / STD A/Rim or

Tyre Size: F: **195/65R15**

        R: **195/65R15**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or   **Habileed**

Front		Rear	
R/Bal. **06** mm		R/Bal. **06** mm	
L/Bal. **06** mm		L/Bal. **06** mm	

D.O.A.   D.O.I. **24/09/24**

Survey held at   **Bifrost**

Des. of Damages: (Frt) / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TPSCDF
29/10/24	Submit LS $11000, 7 days (Red $11191.78, 50%)
04/11/24	Finalised with Reymart LS $11500, 7 days (Red $12191.78, 51%)
	MV :
	PV :
	Nett :

COE Expiry :

Estimate given during : Yes (✓)

1st Survey   No ( )

Date/Time, File Pass to?   ☐ : Preli. Report

1) 05/11 Typist   ☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format :   **TP**

Remark Form / LPO (✓)

Days Of Repair: **7**

Resurvey No. of Trip: **2**

Add Fee: ☐ : Site Insp ($)

     ☐ : Interview ($)

     ☐ : Tech. Inve ($)

Survey Fee:

Transportation:

   S + RS ___ SI

Photos

Others

BIFROST AUTO PTE LTD
8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT
#01-49 SINGAPORE 415875
Tel: +65 64524457
Fax: +65 64524584

Vehicle number: SMV9577Z
Make & Model: Toyota Voxy Hybrid
Chassis number: ZWR800404189

No.	Description of spare parts	Qty	Amount S$
1	Bonnet Dented	1	$ 1,093.20
2	Bonnet lock new	1	$ 295.40
3	Bonnet RH hinge Bent	1	$ 88.90
4	Bonnet LH hinge	1	$ 88.90
5	Bonnet inner heat insulator new	1	$ 453.20
6	Bonnet inner heat insulator clips	1set	$ 80.00
7	Front bumper (painted) Dented	1	$ 1,593.10 1050.
8	Front bumper clips new	1set	$ 70.00 30.
9	Front bumper LH fog lamp	1	$ 412.90
10	Front bumper LH fog lamp cover	1	$ 157.80
11	Front bumper LH fog lamp cover chrome	1	$ 202.50
12	Front bumper RH centre PDC sensor new	1	$ 368.90
13	Front bumper LH centre PDC sensor Missing Rqd	1	$ 368.90 260
14	Front bumper LH side PDC sensor new Rqd	1	$ 368.90 260
15	Front bumper lower grille new	1	$ 178.60
16	Front bumper inner sponge crushed	1	$ 231.40
17	Front bumper reinforcement Dented	1	$ 581.90
18	Front bumper reinforcement LH bracket new	1	$ 67.80
19	Front bumper LH retainer new	1	$ 170.85
20	Front bumper RH retainer new	1	$ 170.85
21	Front bumper under cover new	1	$ 132.90
22	LH headlamp assy crushed	1	$ 4,505.60
23	LH headlamp garnish new	1	$ 215.50
24	Front chrome grille crushed	1	$ 860.70
25	Front chrome grille emblem new	1	$ 116.20
26	Front chrome grille clips new	1set	$ 60.00 20
27	Support panel Buckled	1	$ 2,259.10
28	Support panel upper cover new	1	$ 311.20
29	Support panel upper cover clips new	1set	$ 70.00
30	Aircon condenser new	1	$ 1,899.30
31	Radiator assy crushed	1	$ 2,203.10
32	Front LH fender Buckled	1	$ 903.10
33	Front LH fender "Hybrid" emblem new	1	$ 98.00
34	Front LH fender splash shield new	1	$ 244.60
35	Front LH fender splash shield clips new	1set	$ 70.00

		$	20,993.30
Parts less 25%	$	5,248.33
Total:	$	15,744.98

No.	Special Nett Items	Qty	Amount S$
1	Front number plate	1	$ 80.00 +
2	Radiator coolant	1	$ ~~70.00~~ 50

Total: $ 150.00

No.	Labour and painting	Amount S$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	$ 1,500.00 800
2	Spray painting on affected areas and panels	$ 1,400.00 1800
3	Check wiring and lighting system on affected areas	$ ~~70.00~~ 30
4	Apply rust coating chemical on affected areas and panels	$ ~~70.00~~ 50
5	Remove and replace front bumper PDC sensors to assist repair	$ ~~120.00~~ 50
6	Remove and replace aircon condenser and pipes to assist repair	$ ~~220.00~~ 60
7	Remove and replace radiator assy, pipes and hoses to assist repair	$ ~~220.00~~ 60
	Total:	$ 2,100.00

Agreed Amount:_____(Part by Part / Lump sum)
Working days:_____

Spare Parts:	$	15,744.98
Special Nett:	$	150.00
Labour:	$	2,100.00
Total:	$	17,994.98

Adrian L
L/S 24/09/24.
07 Days