(08/11/13) wef

ASS. REC. BY: Marcus

REF: CD/111 24090423 / Uua3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBL 6474

at Workshop m/s luusMN

of

Insured: SLX 3365J

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: 88k.

IDAC Accident Rport: Consistent? : **Yes** or **No**

GIA / PR Seen: Consistent? : **Yes** or **No**

Est. Repairs: 10 days Res.: **Yes** or **No**

Lum Sum: 20 % 3 Val.: **Yes** or **No**

CA / REV / REP. / 24 HRS C 196N

Vehicle: **IN / OUT**

Date: Person Contacted: LIA 8 19473

Veh No: GBL 6474 Yr Regn: 26/07/21

Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer** or CM/

Make: Toyota hiace c.c 2982

Colour Black A/C: **Insured / Std / NI / NA**

Sp.Reading 43177 T/Radio: **Insured / Std / NI / NA**

Eng/No:

C/No: JTFHT02P800251392

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: **Inorder / Jammed / Leaked / Burnt** or

Brake: **Inorder / Jammed / Leaked / Burnt** or

Modi : **Nil / S/Rim / STD A/Rim** or

Tyre Size: **F:** 195-R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Austone

Front			Rear		
R/Bal.	6	mm	R/Bal.	6	mm
L/Bal.	6	mm	L/Bal.	6	mm

D.O.A. 20/09/24 D.O.I. 24/9/24

Survey held at

Des. of Damages : **Frt / Rear / O/S / N/S / U/C / Rooftop** or Rear o/s

The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
14/10/24	L/S $7400 Op 13k informed Susan

Date/Time, File **Pass** to? : **Preli. Report**

1) : **Final Report**

Date/Time, File **Return** to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: : Site Insp ($)

: Interview ($)

: Tech. Invs ($)

: Weekend ($)

Survey Fee:

Transportation:

__S + RS,__SI

Photos

Others

Report Format :

Lump Sum / I.B.I: ($)

Liu's Brother Auto Workshop
No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

UEN & GST No: 42674600K liusbro@ymail.com
Tel: 67411730

ESTIMATE

Name: India International Insurance Pte Ltd
Address: Motor Claims Department
64 Cecil Street #04-00 & #05-00
IOB Building Singapore 049711

Ref Date: 23/09/2024
Ref No: GBL647Y240920
Vehicle No: GBL647Y
Model / Make: Toyota Hiace Van Turbo 4 DR AT
Capacity: 2982 cc

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Rear	Tailgate	$ 2,759.10	1	$ 2,759.10		[illegible]
2		"Toyota" Motif	$ 82.60	1	$ 82.60		[illegible]
3		Tailgate Lock	$ 399.20	1	$ 399.20		[illegible] X
4		Tailgate Weatherstrip	$ 388.50	1	$ 388.50		[illegible]
5		Bumper	$ 681.40	1	$ 681.40		[illegible]
6		Bumper Clips 1 set	$ 65.00	1	$ 65.00	SN	[illegible] 30 S/N
7		Bumper Reverse Sensor	$ 220.00	1	$ 220.00	SN	[illegible] 200 S/N
8	Rear Rh	Bumper Side Holder o/s	$ 66.50	1	$ 66.50		[illegible]
9		Bumper Lower Bracket o/s	$ 32.80	1	$ 32.80		[illegible]
10		Tail Lamp o/s	$ 408.20	1	$ 408.20		[illegible]
11		Tail Lamp Lower Garnish o/s	$ 161.80	1	$ 161.80		[illegible]
12		Tail Lamp Lower Garnish Bracket o/s	$ 60.80	1	$ 60.80		[illegible]
13		Tail Lamp Housing Panel o/s	$ 728.20	1	$ 728.20		[illegible]
14		Tail Lamp Inner Housing Panel o/s	$ 455.80	1	$ 455.80		[illegible]
15		Fender (Body Panel) o/s	$ 2,039.20	1	$ 2,039.20		[illegible]
16		Fender Inner Panel o/s	$ 1,655.30	1	$ 1,655.30		R X
17		Air Vent o/s	$ 48.60	1	$ 48.60		[illegible]
18		Exhaust	$ 850.80	1	$ 850.80		R X
19		Fender Inner Trim Board o/s	$ 248.20	1	$ 248.20		[illegible]
20		End Panel Inner	$ 936.20	1	$ 936.20		R X
21		End Panel Outer	$ 566.10	1	$ 566.10		R X
22		End Panel Top Steel Plate	$ 211.80	1	$ 211.80		[illegible] X
23		End Panel Sealant	$ 50.00	1	$ 50.00	SN	[illegible] X
24		Tailgate "70 KM/H" Sticker	$ 15.00	1	$ 15.00	SN	[illegible] 10 S/N
25		Tailgate "8 PAX" Sticker	$ 15.00	1	$ 15.00	SN	[illegible] 10 S/N
26		Tailgate Windscreen Sealant	$ 50.00	1	$ 50.00	SN	[illegible] 40 S/N
					[illegible]		
		C/F Balance ---->			**$ 13,196.10**		

Not Authorised [illegible]
24/9/24
d/s $ 7400/
[illegible] photo attempt [illegible] days.

Liu's Brother Auto Workshop

Liu's Brother Auto Workshop
No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883
UEN & GST No: 42674600K liusbro@ymail.com
Tel: 67411730

ESTIMATE

Name: India International Insurance Pte Ltd
Addres: Motor Claims Department
64 Cecil Street #04-00 & #05-00
IOB Building Singapore 049711

Ref Date: 23/09/2024
Ref No: GBL647Y240920
Vehicle No: GBL647Y
Model / Make: Toyota Hiace
Capacity: 2982 cc Van Turbo 4 DR AT

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
		B/F Balance --->			$ 13,196.10		
27		Rear Tailgate "Corporate" Advertisement & Artwork			$ 450.00	SN	Nett 200 S/N
28		Rear Fender "Corporate" Advertisement & Artwork			$ 680.00	SN	Nett 350 S/N
29		To check all wiring & electrical component for proper function			$ 50.00		20
30		Remove and ~~refix~~ replace rear bumper reverse sensor			$ 80.00		30
31		Remove & reinstall Tailgate Windscreen Glass to facilitate repairs			$ 120.00		100
32		Remove and refix rear tailgate components & mechanism			$ 100.00		50
33		Remove and replace rear exhaust pipe system to faciltate repairs			$ 100.00		n/x
34		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs			$ 1,800.00		1200
35		To putty & spray painting & including touch up paint on accident affectecd areas			$ 1,500.00		900
36		To apply Rust Proofing , reseal tuff-coating treatment on accident area			$ 100.00		80

Total Parts & Labour of estimate for damaged vehicle	**Sub-Total**	$ 18,176.10	
Total amount in Lumpsum Basis for repaired vehicle			
GST TAX	**9.00%**	$ 1,635.85	
Grand Total		$ 19,811.95	

SDL _____

Liu's Brother Auto Workshop

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

r- 8161.7
25%
6171.28
840
2380
9341.28