LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SKW 9443U

Qty	Description of Parts	Condition	Workshop Estimate ($)	Our Adjusted ($)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	BUCKLED	$917.90	$917.90
1	FRONT BUMPER LH SIDE RETAINER	DISTORTED	$153.50	$153.50
1	FRONT BUMPER LH CORNAL PARKING SENSOR	DENTED/SHORTED	$555.20	$510.80
6	FRONT BUMPER CLIP @$4.50	NECESSARY	$27.00	$27.00
1	FRONT BUMPER LH QUARTER GARNISH	SERVICEABLE	$84.10	$0.00
1	HEADLAMP LH	MTG CRACKED	$1,807.30	$1,807.30
1	FRONT LH FENDER EMBLEM 'VVTI'	NECESSARY	$70.60	$70.60
1	FRONT LH FENDER	BUCKLED	$1,318.90	$1,318.90
	LESS 25.00% DISCOUNT		($1,233.63)	($1,201.50)
			$3,700.87	$3,604.50

	Description of Parts	Condition	Workshop Estimate ($)	Our Adjusted ($)
	Labour			
	REMOVE & REFIX FRT BUMPER ASSY, GRILLE, HEADLAMPS, FRT LH FENDER; TO KNOCKING & REPAIR FRT SUPPORT PANEL & REALIGN THE SAME		$400.00	$400.00
	PUTTY & RESPRAY ON FRT BUMPER, FRT LH FENDER, FRT SUPPORT PANEL		$600.00	$500.00
			$1,000.00	$900.00

GRAND TOTAL			**$4,700.87**	**$4,504.50**
RECOMMENDED COST OF LUMP SUM REPAIRS **(TO ITS PRE-ACCIDENT CONDITION)**				**$3,600.00**
Report Ref No: CS/FCI24090430/Knp3e2				

MARKET VALUE: $30,000.00 (EST)-LTA REIMBURSEMENT VALUE: $23,549.00=NETT VALUE: $6,451.00

KSC

KENNETH KONG SENG CHEONG